
raw
T1
[1,2]
loading
load_done
T2
[2,3]
wait machine
T5
[0,1]
processing
machining_done
T6
[8,12]
wait transfer
T7
[1,2]
transfer
transfer_done
T8
[2,3]
wait inspect
T9
[0,1]
inspecting
inspection_pass
T10
[4,6]
wait unload
T14
[1,2]
unloading
unload_done
T15
[2,3]
completed
T3
[0,1]
grip recovery
T4
[3,4]
machine free
robot free
rework transfer
T13
[2,3]
rework_returned
rework queue
T12
[1,2]
T11
[4,6]
inspection_rework
inspect free