
Deviation from mean (%)
20
10
0
−10
−20
−100
−80
−60
−40
−20
0
Hours before failure
C1 (voltage)
C2 (rotation)
C3 (pressure)
C4 (vibration)