






Page	Index
1	Cover Sheet
2	Row A/B
3	Row C/D
4	LAN-RJ45 + USB2.0
5	USB2.0 + USB3.0
6	USB3.0 Redriver
7	SATA
8	Audio
9	PCle x4 / x1 Slots
10	MINI CARD_Clock Buffer
11	PCI Express Graphic
12	LVDS
13	VGA + DDI1
14	DP Port
15	CANBUS / SMBUS / I2C
16	RESET + PWROK
17	SIO Card SLOT
18	Serial port + LPC
19	SPI + Buzzer + FAN + RTC
20	ATX Power + Front Panel
21	+5V_DUAL / +3V3_DUAL
22	+12V / +5V / +3V3
23	SATA/USB Switch
24	DDI0/LVDS/CRT Switch
25	LPC 80H
26	Power Block
27	Revision History
Toobnolo	any INC










































































Change History

ltem	Date	Revision	Description	Page	Design By	Approve By
1	2012/12/03	A0.1	First Release.	1 ~ 28	Ronald Lin	Richard Wu
	2013/03/25		1.Add U59,C312,R559,CN67 for USB 2.0 Switch.	4	Ronald Lin	Richard Wu
2		A0.2	1.Add U60,C314,C313,C315,R317,R316,R312,R310,R517,R331,R519,R518,R224,R223,R330,CN22 for SATA Switch.	7		
			1.Codec Power change from +5V to +5V_DUAL.	8		
			1.Add Q50,R561. 2.Change Q47 to AP2305GN.	10		
			1.Change DP Port AC CAP from 0 ohm to 0.1uF.	14		
		 	1.Change SIO Slot pin define and add SUS_S3#,SUS_S5 signal.	17		
			1.ADD R557,R558.	18		
	2013/07/23		1.Chang U25 from ICS9DB108BFLF to 9DB833AFLF. 2.Add Q57,R532.	10		
			1.Remove C324,C325,C334,C335. 2.Add R562,R563,R564,R565.	14		
			1.Change R44,R220,R221,R225 from 1K to 100K. 2.Add R50,R179,R182,R183,R184,R185,R186,R187,R188,R200,R201,R204,R205,R206,R207,R208	3		
		A0.3	1.Add Q54,Q55,R460,R245,R458,R248.	20		
3			1.Reserve R277,R515.	8	Ronald Lin	Richard Wu
			1.Change DDI1 connector to DP connector.	13		
			1.Add U68,U69,C193,C273,C274,C276,R430,R431.	15		
			1.Change DDI0 connector to DP connector. 24 2.Add R210.			
			1.Modify smart FAN circuit.			
			1.Add R575.	12		
3	2013/10/25	A1.0	1.Change R150 connect to B31 of CN19.	9	Ronald Lin	Richard Wu

	AAEON Technology INC.							
MEON®	Title	Rev	vision History					
	Size		ument Number			Rev		
An /5U5 Company	В	B ECB-920A				A1.0_0_0		
	Date:	Frida	v, October 25, 2013	Sheet	27	of	28	
2				1				

