





# ECB-980A COM Express HPC Carrier Board




Page	Index	
1	Cover Page & Block Diagram	
2	Power Map	
3	DP(DDI1) to VGA(CH7517)	
4	VGA	
5	USB2.0	
6	DP 1.4_Redriver & DP	
7	DP 1.4_Redriver & DP	
8	LAN with USB3.1	
9	LAN with USB3.1	
10	SATA/RTC/FAN	
11	Serial port(RS-232)	
12	USB3.1 GEN2 Redriver	
13	USB3.1 GEN2 Redriver	
14	SPI. Clock buffer	
15	BUTTON/PLRST/LED/SMBUS	
16	COM-HPC_Row AB/CD	
17	COM-HPC_Row EF/GH	
18	+3V3_DUAL & +5V_DUAL	
19	F85280 + eSPI 80H	
20	ATX Power + Discharge	
21	PCIEX16 M.2. eDP connecto	
22	25Gbe connector	
23	CSI. SNDW/I2S header	
24	Revision History	
25		
26		
27		
28		
29		
30		
31		
32		













USB 2.0

+5V\_DUAL @ 2A
















0	USB	2.0				
	Size B	Document Number ECB-980A		Re A(	ev: ).1_0	_0
ì	Date: Thurs	5	of	24		






































### **BIOS POST code with eSPI**



#### **eSPI** Connector



## **Port Selection**



# **eSPI Chip Selection**





<Variant Name>





A0.1\_0\_0

Sheet: 19 of 24









01. Project code: 02. Model rame ECB-980A 03. Model registor. AD.1.0 1 05. PCB With 1907-980A00 06. PCB With 1907-980A00 06. PCB With 1907-980A00 08. 接板製量: 2 pcs  Revision History  Page 1  Item Page # Title Date Request								
_	Page#	Title	Date	Owner	Issue Description	Solution Description	Rev.	Bug ID
	XX	xxx	xx	xx	xxx	xxx	A01	
			<b>†</b>					1
			<u> </u>					<u> </u>
			<b></b>					
			ļ					
	•••••		<u> </u>					
			·					
								<del> </del>
								<u> </u>
			<u> </u>					<u> </u>
			<u> </u>					<u> </u>
		ļ	ļ					ļ

Revision History
ECB-980A A0.1\_0\_0 PCB: 1907980A00 Date: 2022/03/25

<variant name=""></variant>	
DOMESTIC ACTOR	AAEON Technology INC.
AA EAN®	Revision History
HILVIY	Ris I December Rev
An /BLS Company	Custom ECB-980A A0.1_0_0
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Date: Thursday, April 28, 2022 Sheet 24 of 24