
COM204
Engineering Graphics


by Dr. Chew Kit Wayne

Lecture 1

Introduction to CAD


TO PRINT THE DRAWING & SAVE IN PDF






Go to model→ right click→ From template

Sheetsets




- Copy your drawing from Model sheet
- Paste into the new template sheet


Choose “ Manufacturing metric”









- Change scale
- 1:2 (drawing size reduced by half)
- 2:1 (drawing size double)



Scale the layout, choose the circled point as base point




Filled in title block




Export to PDF and print


Problem #1




Problem #2




Problem #3




Problem #4




Problem #5


1.25
0.25
45°
45°
0.2
0.125
1.25
0.75
0.3
0.5
0.5
0.125
0.375
0.25
45°
0.2
45°
0.25
1.25
1.5


Problem #6




Problem #7



Problem #8


1.0
1.3
45°
45°
1.0
1.5
2.2
1.4
1.6
60°
150°
2.3
2.1
120°
150°
4.5,2.2
1.4
2.3
1,1
4.1,1
ASSIGNMENT #3 – ACCURATE INPUT
SET-UP: UNITS=DECIMAL / AREA= 10"X7"

Problem #9



CAD Software Provides Additional Layout Benefits