CPC COOPERATIVE PATENT CLASSIFICATION

В PERFORMING OPERATIONS; TRANSPORTING

(NOTES omitted)

TRANSPORTING

B64 AIRCRAFT; AVIATION; COSMONAUTICS

B64U UNMANNED AERIAL VEHICLES [UAV]; EQUIPMENT THEREFOR

NOTES

- 1. This subclass covers:
 - vehicles which are specially adapted for unmanned aeronautical use and the equipment therefor.
- 2. This subclass does not cover:
 - computer control systems for the control of position, course, altitude or attitude, which are covered by group G05D 1/00;
 - traffic control of UAVs, which is covered by group G08G 5/00.
- 3. Aircraft or equipment applicable to both manned and unmanned use should be classified in this subclass and in the subclasses of class **B64** which are appropriate for the manned use.
- 4. Details or features of UAVs and their equipment which are not covered by this subclass should be classified in the relevant subclasses of class B64.
- 5. In this subclass it is desirable to add the indexing codes of group B64U 2101/00, covering particular uses or applications of the UAVs.

10/00 Type of UAV

WARNING

Group B64U 10/00 is incomplete pending reclassification of documents from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, B64C 1/069, B64C 27/08, B64C 27/10,

B64C 27/20, B64C 39/00, B64C 39/001,

B64C 39/003, B64C 39/005, B64C 39/006,

B64C 39/008, B64C 39/02, B64C 39/024 and

B64C 39/029.

Group B64U 10/00 is also impacted by reclassification into groups

B64U 10/10 - B64U 10/17, B64U 10/20,

B64U 10/25, B64U 10/30, B64U 10/40,

B64U 10/50, B64U 10/60, B64U 10/70,

<u>B64U 10/80, B64U 20/00</u> - <u>B64U 20/</u>98,

B64U 30/00 - B64U 30/40,

B64U 40/00 - B64U 40/20,

B64U 50/00 - B64U 50/39,

B64U 60/00 - B64U 60/70,

B64U 70/00 - B64U 70/99 and

B64U 80/00 - B64U 80/86.

All groups listed in this Warning should be considered in order to perform a complete search. 10/10 . Rotorcrafts

WARNING

Group B64U 10/10 is incomplete pending reclassification of documents from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, B64C 1/069, B64C 27/08, B64C 27/10, B64C 27/20, B64C 39/00, B64C 39/001, B64C 39/003, B64C 39/005, B64C 39/006, B64C 39/008, B64C 39/02, B64C 39/024, B64C 39/029 and B64U 10/00.

Group B64U 10/10 is also impacted by reclassification into groups B64U 10/11, B64U 10/13 - B64U 10/16 and B64U 10/17.

All groups listed in this Warning should be considered in order to perform a complete search.

10/11 . . Autogyros

WARNING

Group B64U 10/11 is incomplete pending reclassification of documents from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, B64C 1/069, B64C 27/08, B64C 27/10, B64C 27/20, B64C 39/00, B64C 39/001, B64C 39/003, B64C 39/005, B64C 39/006, B64C 39/008, B64C 39/02, B64C 39/024, B64C 39/029, B64U 10/00 and B64U 10/10.

All groups listed in this Warning should be considered in order to perform a complete search.

10/13 . . Flying platforms

WARNING

Group B64U 10/13 is incomplete pending reclassification of documents from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, B64C 1/069, B64C 27/08, B64C 27/10, B64C 27/20, B64C 39/00, B64C 39/001, B64C 39/003, B64C 39/005, B64C 39/006, B64C 39/008, B64C 39/02, B64C 39/024, B64C 39/029, B64U 10/00 and B64U 10/10. Group B64U 10/13 is also impacted by reclassification into groups B64U 10/14 and B64U 10/16.

All groups listed in this Warning should be considered in order to perform a complete search

10/14 . . . with four distinct rotor axes, e.g. quadcopters

WARNING

Group B64U 10/14 is incomplete pending reclassification of documents from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, B64C 1/069, B64C 27/08, B64C 27/10, B64C 27/20, B64C 39/00, B64C 39/001, B64C 39/003, B64C 39/005, B64C 39/006, B64C 39/008, B64C 39/02, B64C 39/024, B64C 39/029, B64U 10/00, B64U 10/10 and B64U 10/13.

All groups listed in this Warning should be considered in order to perform a complete search.

10/16 . . . with five or more distinct rotor axes, e.g. octocopters

WARNING

Group <u>B64U 10/16</u> is incomplete pending reclassification of documents from groups <u>B64C 1/00</u>, <u>B64C 1/0009</u>, <u>B64C 1/06</u>, <u>B64C 1/061</u>, <u>B64C 1/062</u>, <u>B64C 1/063</u>, <u>B64C 1/064</u>, <u>B64C 1/065</u>, <u>B64C 1/068</u>, <u>B64C 1/069</u>, <u>B64C 27/08</u>, <u>B64C 27/10</u>, <u>B64C 27/20</u>, <u>B64C 39/00</u>, <u>B64C 39/001</u>, <u>B64C 39/003</u>, <u>B64C 39/005</u>, <u>B64C 39/006</u>, <u>B64C 39/008</u>, <u>B64C 39/024</u>, <u>B64C 39/029</u>, <u>B64U 10/10</u>, <u>B64U 10/10</u> and <u>B64U 10/13</u>

All groups listed in this Warning should be considered in order to perform a complete search.

10/17 . Helicopters (flying platforms <u>B64U 10/13</u>)

WARNING

Group B64U 10/17 is incomplete pending reclassification of documents from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, B64C 1/069, B64C 27/08, B64C 27/10, B64C 27/20, B64C 39/00, B64C 39/001, B64C 39/003, B64C 39/005, B64C 39/006, B64C 39/008, B64C 39/02, B64C 39/024, B64C 39/029, B64U 10/00 and B64U 10/10. All groups listed in this Warning should be

considered in order to perform a complete

search.

10/20
• Vertical take-off and landing [VTOL] aircraft (flying platforms B64U 10/13; helicopters

WARNING

B64U 10/17)

Group <u>B64U 10/20</u> is incomplete pending reclassification of documents from groups <u>B64C 1/00</u>, <u>B64C 1/0009</u>, <u>B64C 1/06</u>, <u>B64C 1/061</u>, <u>B64C 1/062</u>, <u>B64C 1/063</u>, <u>B64C 1/064</u>, <u>B64C 1/065</u>, <u>B64C 1/068</u>, <u>B64C 1/069</u>, <u>B64C 27/08</u>, <u>B64C 27/10</u>, <u>B64C 27/20</u>, <u>B64C 39/00</u>, <u>B64C 39/001</u>, <u>B64C 39/003</u>, <u>B64C 39/005</u>, <u>B64C 39/006</u>, <u>B64C 39/008</u>, <u>B64C 39/029</u>, <u>B64C 39/024</u>, <u>B64C 39/029</u> and <u>B64U 10/00</u>.

All groups listed in this Warning should be considered in order to perform a complete search.

10/25 • Fixed-wing aircraft (VTOL aircraft <u>B64U 10/20</u>)

WARNING

Group <u>B64U 10/25</u> is incomplete pending reclassification of documents from groups <u>B64C 1/00</u>, <u>B64C 1/0009</u>, <u>B64C 1/066</u>, <u>B64C 1/061</u>, <u>B64C 1/062</u>, <u>B64C 1/063</u>, <u>B64C 1/064</u>, <u>B64C 1/065</u>, <u>B64C 1/068</u>, <u>B64C 1/069</u>, <u>B64C 27/08</u>, <u>B64C 27/10</u>, <u>B64C 27/20</u>, <u>B64C 39/00</u>, <u>B64C 39/001</u>, <u>B64C 39/003</u>, <u>B64C 39/005</u>, <u>B64C 39/006</u>, <u>B64C 39/008</u>, <u>B64C 39/024</u>, <u>B64C 39/029</u> and <u>B64U 10/00</u>.

Group <u>B64U 10/25</u> is also impacted by reclassification into group <u>B64U 30/10</u>.

All groups listed in this Warning should be considered in order to perform a complete search.

10/30 • Lighter-than-air aircraft, e.g. aerostatic aircraft

WARNING

Group <u>B64U 10/30</u> is incomplete pending reclassification of documents from groups <u>B64C 1/00</u>, <u>B64C 1/0009</u>, <u>B64C 1/06</u>, <u>B64C 1/061</u>, <u>B64C 1/062</u>, <u>B64C 1/063</u>, <u>B64C 1/064</u>, <u>B64C 1/065</u>, <u>B64C 1/068</u>, <u>B64C 1/069</u>, <u>B64C 27/08</u>, <u>B64C 27/10</u>, <u>B64C 27/20</u>, <u>B64C 39/00</u>, <u>B64C 39/001</u>, <u>B64C 39/003</u>, <u>B64C 39/005</u>, <u>B64C 39/006</u>, <u>B64C 39/008</u>, <u>B64C 39/024</u>, <u>B64C 39/029</u> and <u>B64U 10/00</u>.

All groups listed in this Warning should be considered in order to perform a complete search.

10/40 • Ornithopters

WARNING

Group <u>B64U 10/40</u> is incomplete pending reclassification of documents from groups <u>B64C 1/00</u>, <u>B64C 1/0009</u>, <u>B64C 1/06</u>, <u>B64C 1/061</u>, <u>B64C 1/062</u>, <u>B64C 1/063</u>, <u>B64C 1/064</u>, <u>B64C 1/065</u>, <u>B64C 1/068</u>, <u>B64C 1/069</u>, <u>B64C 27/08</u>, <u>B64C 27/10</u>, <u>B64C 27/20</u>, <u>B64C 33/00</u>, <u>B64C 39/00</u>, <u>B64C 39/001</u>, <u>B64C 39/003</u>, <u>B64C 39/005</u>, <u>B64C 39/006</u>, <u>B64C 39/008</u>, <u>B64C 39/024</u>, <u>B64C 39/029</u> and <u>B64U 10/00</u>.

All groups listed in this Warning should be considered in order to perform a complete search.

10/50 • Glider-type UAVs, e.g. with parachute, parasail or kite (for landing <u>B64U 70/83</u>)

WARNING

Group B64U 10/50 is incomplete pending reclassification of documents from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, B64C 1/069, B64C 27/08, B64C 27/10, B64C 27/20, B64C 39/00, B64C 39/001, B64C 39/003, B64C 39/005, B64C 39/006, B64C 39/008, B64C 39/029, B64C 39/024, B64C 39/029 and B64U 10/00.

All groups listed in this Warning should be considered in order to perform a complete search.

10/60 • Tethered aircraft

WARNING

Group <u>B64U 10/60</u> is incomplete pending reclassification of documents from groups <u>B64C 1/00</u>, <u>B64C 1/0009</u>, <u>B64C 1/06</u>, <u>B64C 1/061</u>, <u>B64C 1/062</u>, <u>B64C 1/063</u>, <u>B64C 1/064</u>, <u>B64C 1/065</u>, <u>B64C 1/068</u>, <u>B64C 1/069</u>, <u>B64C 27/08</u>, <u>B64C 27/10</u>, <u>B64C 27/20</u>, <u>B64C 39/00</u>, <u>B64C 39/001</u>, <u>B64C 39/003</u>, <u>B64C 39/005</u>, <u>B64C 39/002</u>, <u>B64C 39/002</u>, <u>B64C 39/022</u>, <u>B64C 39/024</u>, <u>B64C 39/029</u> and <u>B64U 10/00</u>.

All groups listed in this Warning should be considered in order to perform a complete search.

10/70 • Convertible aircraft, e.g. convertible into land vehicles

WARNING

Group <u>B64U 10/70</u> is incomplete pending reclassification of documents from groups <u>B64C 1/00</u>, <u>B64C 1/0009</u>, <u>B64C 1/06</u>, <u>B64C 1/062</u>, <u>B64C 1/063</u>, <u>B64C 1/064</u>, <u>B64C 1/065</u>, <u>B64C 1/068</u>, <u>B64C 1/069</u>, <u>B64C 27/08</u>, <u>B64C 27/10</u>, <u>B64C 27/20</u>, <u>B64C 39/00</u>, <u>B64C 39/001</u>, <u>B64C 39/003</u>, <u>B64C 39/005</u>, <u>B64C 39/006</u>, <u>B64C 39/008</u>, <u>B64C 39/024</u>, <u>B64C 39/029</u> and <u>B64U 10/00</u>.

All groups listed in this Warning should be considered in order to perform a complete search.

 UAVs characterised by their small size, e.g. micro air vehicles [MAV]

WARNING

10/80

Group B64U 10/80 is incomplete pending reclassification of documents from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, B64C 1/069, B64C 27/08, B64C 27/10, B64C 27/20, B64C 39/00, B64C 39/001, B64C 39/003, B64C 39/005, B64C 39/004, B64C 39/008, B64C 39/024, B64C 39/028, B64C 39/029 and B64U 10/00.

All groups listed in this Warning should be considered in order to perform a complete search.

20/00 Constructional aspects of UAVs (of lift-producing 20/87 . . Mounting of imaging devices, e.g. mounting of means B64U 30/00) gimbals WARNING WARNING Groups B64U 20/00, B64U 20/10, B64U 20/20, Group B64U 20/87 is incomplete pending B64U 20/30, B64U 20/40, B64U 20/60, reclassification of documents from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64U 20/65, B64U 20/70, B64U 20/73, B64C 1/061, B64C 1/062, B64C 1/063, B64U 20/75, B64U 20/77, B64U 20/80, B64C 1/064, B64C 1/065, B64C 1/068, B64U 20/83, B64U 20/90, B64U 20/92, B64U 20/94, B64U 20/96 and B64U 20/98 are <u>B64C 1/069</u>, <u>B64C 27/08</u>, <u>B64C 27/10</u>, incomplete pending reclassification of documents B64C 27/20, B64C 39/00, B64C 39/001, from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64C 39/003, B64C 39/005, B64C 39/006, B64C 39/008, B64C 39/02, B64C 39/024, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, B64C 39/029, B64D 47/08 and B64U 10/00. B64C 1/069, B64C 27/08, B64C 27/10, All groups listed in this Warning should be B64C 27/20, B64C 39/00, B64C 39/001, considered in order to perform a complete B64C 39/003, B64C 39/005, B64C 39/006, B64C 39/008, B64C 39/02, B64C 39/024, B64C 39/029 and B64U 10/00. 20/90 Cooling 20/92 . . of avionics All groups listed in this Warning should be 20/94 . . of rotors or rotor motors considered in order to perform a complete search. 20/96 . . using air 20/10 . for stealth, e.g. reduction of cross-section detectable 20/98 using liquid, e.g. using lubrication oil by radars 30/00 Means for producing lift; Empennages; 20/20 . for noise reduction Arrangements thereof 20/30 • for safety, e.g. with frangible components (rotor guards B64U 30/299) WARNING 20/40 . Modular UAVs Group B64U 30/00 is incomplete pending 20/50 . Foldable or collapsible UAVs (with frangible reclassification of documents from groups components B64U 20/30) B64C 1/00, B64C 1/0009, B64C 1/06, WARNING B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, Group B64U 20/50 is incomplete pending B64C 1/069, B64C 27/08, B64C 27/10, reclassification of documents from groups B64C 27/20, B64C 39/00, B64C 39/001, B64C 1/00, B64C 1/0009, B64C 1/06, B64C 39/003, B64C 39/005, B64C 39/006, B64C 1/061, B64C 1/062, B64C 1/063, B64C 39/008, B64C 39/02, B64C 39/024, B64C 1/064, B64C 1/065, B64C 1/068, B64C 39/029 and B64U 10/00. B64C 1/069, B64C 1/26, B64C 1/30, B64C 3/56, Group B64U 30/00 is also impacted B64C 27/08, B64C 27/10, B64C 27/20, by reclassification into groups B64C 39/00, B64C 39/001, B64C 39/003, B64U 30/10 - B64U 30/16, B64C 39/005, B64C 39/006, B64C 39/008, B64U 30/20 - B64U 30/299, B64U 30/30 and B64C 39/02, B64C 39/024, B64C 39/029 and B64U 30/40. B64U 10/00. All groups listed in this Warning should be All groups listed in this Warning should be considered in order to perform a complete search. considered in order to perform a complete 30/10 . Wings 20/60 . UAVs characterised by the material WARNING 20/65 . . Composite materials Group <u>B64U 30/10</u> is incomplete pending 20/70 . Constructional aspects of the UAV body reclassification of documents from groups 20/73 . . Monocoque body B64C 1/00, B64C 1/0009, B64C 1/06, 20/75 . . the body formed by joined shells or by a shell B64C 1/061, B64C 1/062, B64C 1/063, overlaying a chassis B64C 1/064, B64C 1/065, B64C 1/068, 20/77 . . the body being formed integrally with wings or B64C 1/069, B64C 27/08, B64C 27/10, rotor supports B64C 27/20, B64C 39/00, B64C 39/001, . Arrangement of on-board electronics, e.g. avionics 20/80 B64C 39/003, B64C 39/005, B64C 39/006, systems or wiring B64C 39/008, B64C 39/02, B64C 39/024, 20/83 . . Electronic components structurally integrated B64C 39/029, B64U 10/00, B64U 10/25 and with aircraft elements, e.g. circuit boards carrying B64U 30/00. loads Group B64U 30/10 is also impacted by reclassification into groups B64U 30/12 - B64U 30/16. All groups listed in this Warning should be

CPC - 2024.05

considered in order to perform a complete

search.

30/12 . Variable or detachable wings, e.g. wings with adjustable sweep

WARNING

Group B64U 30/12 is incomplete pending reclassification of documents from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, B64C 1/069, B64C 1/26, B64C 1/30, B64C 3/56, B64C 27/08, B64C 27/10, B64C 27/20, B64C 39/00, B64C 39/001, B64C 39/003, B64C 39/005, B64C 39/006, B64C 39/008, B64C 39/002, B64C 39/004, B64C 39/029, B64U 10/00, B64U 30/00 and B64U 30/10.

Group $\underline{B64U\ 30/12}$ is also impacted by reclassification into groups $\underline{B64U\ 30/14}$ and $\underline{B64U\ 30/16}$.

All groups listed in this Warning should be considered in order to perform a complete search.

30/14 . . . detachable

WARNING

Group <u>B64U 30/14</u> is incomplete pending reclassification of documents from groups <u>B64C 1/00</u>, <u>B64C 1/0009</u>, <u>B64C 1/06</u>, <u>B64C 1/061</u>, <u>B64C 1/062</u>, <u>B64C 1/063</u>, <u>B64C 1/064</u>, <u>B64C 1/065</u>, <u>B64C 1/068</u>, <u>B64C 1/069</u>, <u>B64C 1/26</u>, <u>B64C 1/30</u>, <u>B64C 3/56</u>, <u>B64C 27/08</u>, <u>B64C 27/10</u>, <u>B64C 27/20</u>, <u>B64C 39/00</u>, <u>B64C 39/001</u>, <u>B64C 39/003</u>, <u>B64C 39/005</u>, <u>B64C 39/006</u>, <u>B64C 39/008</u>, <u>B64C 39/024</u>, <u>B64C 39/029</u>, <u>B64U 10/00</u>, <u>B64U 30/00</u>, <u>B64U 30/10</u> and <u>B64U 30/12</u>.

All groups listed in this Warning should be considered in order to perform a complete search

30/16 . . . movable along the UAV body

WARNING

Group <u>B64U 30/16</u> is incomplete pending reclassification of documents from groups <u>B64C 1/00</u>, <u>B64C 1/0009</u>, <u>B64C 1/06</u>, <u>B64C 1/061</u>, <u>B64C 1/062</u>, <u>B64C 1/063</u>, <u>B64C 1/064</u>, <u>B64C 1/065</u>, <u>B64C 1/068</u>, <u>B64C 1/069</u>, <u>B64C 1/26</u>, <u>B64C 1/30</u>, <u>B64C 3/56</u>, <u>B64C 27/08</u>, <u>B64C 27/10</u>, <u>B64C 27/20</u>, <u>B64C 39/00</u>, <u>B64C 39/001</u>, <u>B64C 39/003</u>, <u>B64C 39/005</u>, <u>B64C 39/006</u>, <u>B64C 39/008</u>, <u>B64C 39/024</u>, <u>B64C 39/029</u>, <u>B64U 10/00</u>, <u>B64U 30/00</u>, <u>B64U 30/10</u> and <u>B64U 30/12</u>.

All groups listed in this Warning should be considered in order to perform a complete search.

30/20 . Rotors; Rotor supports

WARNING

Group <u>B64U 30/20</u> is incomplete pending reclassification of documents from groups <u>B64C 1/00</u>, <u>B64C 1/0009</u>, <u>B64C 1/06</u>, <u>B64C 1/061</u>, <u>B64C 1/062</u>, <u>B64C 1/063</u>, <u>B64C 1/064</u>, <u>B64C 1/065</u>, <u>B64C 1/068</u>, <u>B64C 1/069</u>, <u>B64C 27/08</u>, <u>B64C 27/10</u>, <u>B64C 27/20</u>, <u>B64C 39/00</u>, <u>B64C 39/001</u>, <u>B64C 39/003</u>, <u>B64C 39/005</u>, <u>B64C 39/004</u>, <u>B64C 39/029</u>, <u>B64C 39/029</u>, <u>B64C 39/024</u>, <u>B64C 39/029</u>, <u>B64U 10/00</u> and <u>B64U 30/00</u>. Group <u>B64U 30/20</u> is also impacted by reclassification into groups <u>B64U 30/21</u>, <u>B64U 30/24</u>, <u>B64U 30/26</u>, <u>B64U 30/27</u> and <u>B64U 30/29</u> - <u>B64U 30/299</u>.

All groups listed in this Warning should be considered in order to perform a complete search.

30/21 . Rotary wings

WARNING

Group <u>B64U 30/21</u> is incomplete pending reclassification of documents from groups <u>B64C 1/00</u>, <u>B64C 1/0009</u>, <u>B64C 1/06</u>, <u>B64C 1/061</u>, <u>B64C 1/062</u>, <u>B64C 1/063</u>, <u>B64C 1/064</u>, <u>B64C 1/065</u>, <u>B64C 1/068</u>, <u>B64C 1/069</u>, <u>B64C 27/08</u>, <u>B64C 27/10</u>, <u>B64C 27/20</u>, <u>B64C 39/00</u>, <u>B64C 39/001</u>, <u>B64C 39/003</u>, <u>B64C 39/005</u>, <u>B64C 39/006</u>, <u>B64C 39/008</u>, <u>B64C 39/029</u>, <u>B64C 39/024</u>, <u>B64C 39/029</u>, <u>B64U 10/00</u>, <u>B64U 30/00</u> and <u>B64U 30/20</u>.

All groups listed in this Warning should be considered in order to perform a complete search.

30/24 . . Coaxial rotors

WARNING

Group B64U 30/24 is incomplete pending reclassification of documents from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, B64C 1/069, B64C 27/08, B64C 27/10, B64C 27/20, B64C 39/00, B64C 39/001, B64C 39/003, B64C 39/005, B64C 39/006, B64C 39/008, B64C 39/024, B64C 39/029, B64U 10/00, B64U 30/00 and B64U 30/20.

All groups listed in this Warning should be considered in order to perform a complete search.

30/26 . . Ducted or shrouded rotors

WARNING

Group B64U 30/26 is incomplete pending reclassification of documents from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, <u>B64C 1/069</u>, <u>B64C 27/08</u>, <u>B64C 27/10</u>, B64C 27/20, B64C 39/00, B64C 39/001, B64C 39/003, B64C 39/005, B64C 39/006, B64C 39/008, B64C 39/02, B64C 39/024, B64C 39/029, B64U 10/00, B64U 30/00 and B64U 30/20.

All groups listed in this Warning should be considered in order to perform a complete

30/27 . . Rim-driven rotors

WARNING

Group B64U 30/27 is incomplete pending reclassification of documents from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, B64C 1/069, B64C 27/08, B64C 27/10, B64C 27/20, B64C 39/00, B64C 39/001, B64C 39/003, B64C 39/005, B64C 39/006, B64C 39/008, B64C 39/02, B64C 39/024, B64C 39/029, B64U 10/00, B64U 30/00 and B64U 30/20.

All groups listed in this Warning should be considered in order to perform a complete search.

30/29 . . Constructional aspects of rotors or rotor supports; Arrangements thereof

WARNING

Groups <u>B64U 30/29</u> - <u>B64U 30/299</u> are incomplete pending reclassification of documents from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, B64C 1/069, B64C 27/08, B64C 27/10, B64C 27/20, B64C 39/00, B64C 39/001, B64C 39/003, B64C 39/005, B64C 39/006, B64C 39/008, B64C 39/02, B64C 39/024, B64C 39/029, B64U 10/00, B64U 30/00 and B64U 30/20.

All groups listed in this Warning should be considered in order to perform a complete search.

30/291 . . . Detachable rotors or rotor supports

30/292 . . . Rotors or rotor supports specially adapted for quick release

30/293 . . . Foldable or collapsible rotors or rotor supports

. . . Rotors arranged in the UAV body 30/294

. . . Rotors arranged in the wings 30/295

30/296 . . . Rotors with variable spatial positions relative to the UAV body (foldable or collapsible rotors B64U 30/293)

30/297 . . . Tilting rotors 30/298 . . . Helicopter flybars 30/299 . . . Rotor guards (ducted or shrouded rotors B64U 30/26; guards used as ground propulsion B64U 60/60)

30/30 . Lift-producing means using radial airflow

WARNING

Group B64U 30/30 is incomplete pending reclassification of documents from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, B64C 1/069, B64C 27/08, B64C 27/10, B64C 27/20, B64C 39/00, B64C 39/001, B64C 39/003, B64C 39/005, B64C 39/006, B64C 39/008, B64C 39/02, B64C 39/024, B64C 39/029, B64U 10/00 and B64U 30/00. All groups listed in this Warning should be

considered in order to perform a complete search.

30/40 . Empennages, e.g. V-tails (foldable or collapsible UAVs B64U 20/50)

WARNING

Group B64U 30/40 is incomplete pending reclassification of documents from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, B64C 1/069, B64C 27/08, B64C 27/10, B64C 27/20, B64C 39/00, B64C 39/001, B64C 39/003, B64C 39/005, B64C 39/006, B64C 39/008, B64C 39/02, B64C 39/024, B64C 39/029, B64U 10/00 and B64U 30/00.

All groups listed in this Warning should be considered in order to perform a complete search.

40/00

On-board mechanical arrangements for adjusting control surfaces or rotors; On-board mechanical arrangements for in-flight adjustment of the base configuration (control of position, course, altitude or attitude of air or space vehicles, e.g. automatic pilot, G05D 1/00)

WARNING

Groups <u>B64U 40/00</u> - <u>B64U 40/20</u> are incomplete pending reclassification of documents from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, B64C 1/069, B64C 27/08, B64C 27/10, B64C 27/20, B64C 39/00, B64C 39/001, B64C 39/003, B64C 39/005, B64C 39/006, B64C 39/008, B64C 39/02, B64C 39/024, B64C 39/029 and B64U 10/00.

All groups listed in this Warning should be considered in order to perform a complete search.

40/10 . for adjusting control surfaces or rotors

40/20 . for in-flight adjustment of the base configuration

50/00 **Propulsion**; Power supply 50/14 . . . ducted or shrouded WARNING WARNING Group B64U 50/00 is incomplete pending Group B64U 50/14 is incomplete pending reclassification of documents from groups reclassification of documents from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, B64C 1/064, B64C 1/065, B64C 1/068, B64C 1/069, B64C 27/08, B64C 27/10, <u>B64C 1/069</u>, <u>B64C 27/08</u>, <u>B64C 27/10</u>, B64C 27/20, B64C 39/00, B64C 39/001, <u>B64C 27/20</u>, <u>B64C 39/00</u>, <u>B64C 39/0</u>01, B64C 39/003, B64C 39/005, B64C 39/006, B64C 39/003, B64C 39/005, B64C 39/006, B64C 39/008, B64C 39/02, B64C 39/024, B64C 39/008, B64C 39/02, B64C 39/024, B64C 39/029, B64U 10/00, B64U 50/00 and B64C 39/029 and B64U 10/00. B64U 50/13. Group B64U 50/00 is also impacted by reclassification into groups All groups listed in this Warning should be B64U 50/10 - B64U 50/19, considered in order to perform a complete B64U 50/20 - B64U 50/27 and B64U 50/30 - B64U 50/39 50/15 . . using combustion exhausts other than turbojets or All groups listed in this Warning should be turbofans, e.g. using rockets, ramjets, scramjets or considered in order to perform a complete search. pulse-reactors 50/16 . . using means other than air displacement or 50/10 Propulsion (rotors specially adapted for rotorcraft or combustion exhaust, e.g. water or magnetic VTOL <u>B64U 30/20</u>) levitation WARNING 50/18. . Thrust vectoring Groups B64U 50/10, B64U 50/11, B64U 50/12, 50/19 . . using electrically powered motors B64U 50/15, B64U 50/16 and B64U 50/18 WARNING are incomplete pending reclassification of documents from groups B64C 1/00, Group B64U 50/19 is incomplete pending B64C 1/0009, B64C 1/06, B64C 1/061, reclassification of documents from groups <u>B64C 1/062</u>, <u>B64C 1/063</u>, <u>B64C 1/064</u>, B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/065, B64C 1/068, B64C 1/069, B64C 1/061, B64C 1/062, B64C 1/063, B64C 27/08, B64C 27/10, B64C 27/20, B64C 1/064, B64C 1/065, B64C 1/068, B64C 39/00, B64C 39/001, B64C 39/003, B64C 1/069, B64C 27/08, B64C 27/10, B64C 39/005, B64C 39/006, B64C 39/008, B64C 27/20, B64C 39/00, B64C 39/001, B64C 39/02, B64C 39/024, B64C 39/029, B64C 39/003, B64C 39/005, B64C 39/006, B64U 10/00 and B64U 50/00. B64C 39/008, B64C 39/02, B64C 39/024, B64C 39/029, B64U 10/00 and B64U 50/00. All groups listed in this Warning should be considered in order to perform a complete Group B64U 50/19 is also impacted by reclassification into groups search. B64U 50/30 - B64U 50/39. 50/11 . . using internal combustion piston engines All groups listed in this Warning should be 50/12 . . using turbine engines, e.g. turbojets or turbofans considered in order to perform a complete 50/13 . . using external fans or propellers search. WARNING 50/20 . Transmission of mechanical power to rotors or Group B64U 50/13 is incomplete pending propellers reclassification of documents from groups **WARNING** B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 1/062, B64C 1/063, Groups <u>B64U 50/20</u> - <u>B64U 50/27</u> are B64C 1/064, B64C 1/065, B64C 1/068, incomplete pending reclassification of B64C 1/069, B64C 27/08, B64C 27/10, documents from groups B64C 1/00, B64C 27/20, B64C 39/00, B64C 39/001, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 39/003, B64C 39/005, B64C 39/006, B64C 1/062, B64C 1/063, B64C 1/064, B64C 39/008, B64C 39/02, B64C 39/024, B64C 1/065, B64C 1/068, B64C 1/069, B64C 39/029, B64U 10/00 and B64U 50/00. B64C 27/08, B64C 27/10, B64C 27/20, B64C 39/00, B64C 39/001, B64C 39/003, Group B64U 50/13 is also impacted by B64C 39/005, B64C 39/006, B64C 39/008, reclassification into group B64U 50/14. B64C 39/02, B64C 39/024, B64C 39/029, All groups listed in this Warning should be

considered in order to perform a complete search.

All groups listed in this Warning should be

/22

50/23 . with each propulsion means having an individual

B64U 10/00 and B64U 50/00.

CPC - 2024.05

considered in order to perform a complete

search.

 with a single motor serving two or more rotors or propellers

50/30 • Supply or distribution of electrical power

WARNING

Groups B64U 50/30, B64U 50/32 and B64U 50/33 are incomplete pending reclassification of documents from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, B64C 1/069, B64C 27/08, B64C 27/10, B64C 27/20, B64C 39/00, B64C 39/001, B64C 39/003, B64C 39/005, B64C 39/006, B64C 39/008, B64C 39/02, B64C 39/024, B64C 39/029, B64U 10/00, B64U 50/00 and B64U 50/19.

All groups listed in this Warning should be considered in order to perform a complete search.

50/31 . . generated by photovoltaics

WARNING

Group <u>B64U 50/31</u> is incomplete pending reclassification of documents from groups <u>B64C 1/00</u>, <u>B64C 1/0009</u>, <u>B64C 1/06</u>, <u>B64C 1/061</u>, <u>B64C 1/062</u>, <u>B64C 1/063</u>, <u>B64C 1/064</u>, <u>B64C 1/065</u>, <u>B64C 1/068</u>, <u>B64C 1/069</u>, <u>B64C 27/08</u>, <u>B64C 27/10</u>, <u>B64C 27/20</u>, <u>B64C 39/00</u>, <u>B64C 39/001</u>, <u>B64C 39/003</u>, <u>B64C 39/005</u>, <u>B64C 39/006</u>, <u>B64C 39/008</u>, <u>B64C 39/024</u>, <u>B64C 39/029</u>, <u>B64U 10/00</u>, <u>B64U 50/00</u>, <u>B64U 50/19</u> and <u>B64D 27/353</u>.

All groups listed in this Warning should be considered in order to perform a complete search.

50/32 . . generated by fuel cells

50/33 . . generated by combustion engines

• In-flight charging (photovoltaics <u>B64U 50/31</u>)

WARNING

Group B64U 50/34 is incomplete pending reclassification of documents from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, B64C 1/069, B64C 27/08, B64C 27/10, B64C 27/20, B64C 39/00, B64C 39/001, B64C 39/003, B64C 39/005, B64C 39/006, B64C 39/008, B64C 39/02, B64C 39/024, B64C 39/029, B64U 10/00, B64U 50/00 and B64U 50/19.

Group <u>B64U 50/34</u> is also impacted by reclassification into groups <u>B64U 50/35</u>, <u>B64U 50/36</u>, <u>B64U 50/37</u> - <u>B64U 50/38</u> and <u>B64U 50/39</u>.

All groups listed in this Warning should be considered in order to perform a complete search.

50/35 . . . by wireless transmission, e.g. by induction

WARNING

Group <u>B64U 50/35</u> is incomplete pending reclassification of documents from groups <u>B64C 1/00</u>, <u>B64C 1/0009</u>, <u>B64C 1/06</u>, <u>B64C 1/062</u>, <u>B64C 1/063</u>, <u>B64C 1/064</u>, <u>B64C 1/065</u>, <u>B64C 1/068</u>, <u>B64C 1/069</u>, <u>B64C 27/08</u>, <u>B64C 1/068</u>, <u>B64C 27/20</u>, <u>B64C 27/20</u>, <u>B64C 39/00</u>, <u>B64C 39/001</u>, <u>B64C 39/003</u>, <u>B64C 39/005</u>, <u>B64C 39/006</u>, <u>B64C 39/008</u>, <u>B64C 39/024</u>, <u>B64C 39/029</u>, <u>B64U 10/00</u>, <u>B64U 50/00</u>, <u>B64U 50/19</u> and <u>B64U 50/34</u>.

All groups listed in this Warning should be considered in order to perform a complete search.

50/36 . . . by wind turbines, e.g. ram air turbines [RAT]

WARNING

Group <u>B64U 50/36</u> is incomplete pending reclassification of documents from groups <u>B64C 1/00</u>, <u>B64C 1/0009</u>, <u>B64C 1/06</u>, <u>B64C 1/061</u>, <u>B64C 1/062</u>, <u>B64C 1/063</u>, <u>B64C 1/064</u>, <u>B64C 1/065</u>, <u>B64C 1/068</u>, <u>B64C 1/069</u>, <u>B64C 27/08</u>, <u>B64C 27/10</u>, <u>B64C 27/20</u>, <u>B64C 39/00</u>, <u>B64C 39/001</u>, <u>B64C 39/003</u>, <u>B64C 39/005</u>, <u>B64C 39/006</u>, <u>B64C 39/008</u>, <u>B64C 39/024</u>, <u>B64C 39/029</u>, <u>B64U 10/00</u>, <u>B64U 50/00</u>, <u>B64U 50/19</u> and <u>B64U 50/34</u>.

All groups listed in this Warning should be considered in order to perform a complete search.

50/37 . . Charging when not in flight

WARNING

Groups <u>B64U 50/37</u> and <u>B64U 50/38</u> are incomplete pending reclassification of documents from groups <u>B64C 1/00</u>, <u>B64C 1/009</u>, <u>B64C 1/06</u>, <u>B64C 1/063</u>, <u>B64C 1/064</u>, <u>B64C 1/065</u>, <u>B64C 1/063</u>, <u>B64C 1/069</u>, <u>B64C 27/08</u>, <u>B64C 27/10</u>, <u>B64C 27/20</u>, <u>B64C 39/00</u>, <u>B64C 39/001</u>, <u>B64C 39/003</u>, <u>B64C 39/005</u>, <u>B64C 39/004</u>, <u>B64C 39/008</u>, <u>B64C 39/024</u>, <u>B64C 39/029</u>, <u>B64U 10/00</u>, <u>B64U 50/00</u>, <u>B64U 50/19</u> and <u>B64U 50/34</u>.

All groups listed in this Warning should be considered in order to perform a complete search.

50/38 . . . by wireless transmission

50/39 . . Battery swapping

WARNING

Group <u>B64U 50/39</u> is incomplete pending reclassification of documents from groups <u>B64C 1/00</u>, <u>B64C 1/0009</u>, <u>B64C 1/06</u>, <u>B64C 1/062</u>, <u>B64C 1/063</u>, <u>B64C 1/064</u>, <u>B64C 1/065</u>, <u>B64C 1/063</u>, <u>B64C 1/069</u>, <u>B64C 27/08</u>, <u>B64C 27/10</u>, <u>B64C 27/20</u>, <u>B64C 39/00</u>, <u>B64C 39/001</u>, <u>B64C 39/003</u>, <u>B64C 39/005</u>, <u>B64C 39/006</u>, <u>B64C 39/008</u>, <u>B64C 39/024</u>, <u>B64C 39/029</u>, <u>B64U 10/00</u>, <u>B64U 50/00</u>, <u>B64U 50/19</u> and <u>B64U 50/34</u>.

All groups listed in this Warning should be considered in order to perform a complete search

60/00 Undercarriages

WARNING

Groups B64U 60/00 - B64U 60/70 are incomplete pending reclassification of documents from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, B64C 1/069, B64C 27/08, B64C 27/10, B64C 27/20, B64C 39/00, B64C 39/001, B64C 39/003, B64C 39/005, B64C 39/006, B64C 39/008, B64C 39/02, B64C 39/024, B64C 39/029 and B64U 10/00.

All groups listed in this Warning should be considered in order to perform a complete search.

60/10 . specially adapted for use on water

60/20 . specially adapted for uneven terrain

60/30 . detachable from the body

60/40 • foldable or retractable

60/50 • with landing legs

60/55 . . the legs being also used as ground propulsion

60/60 • with rolling cages

60/70

Movable wings, rotor supports or shrouds acting as ground-engaging elements

70/00 Launching, take-off or landing arrangements

WARNING

Group <u>B64U 70/00</u> is incomplete pending reclassification of documents from groups

B64C 1/00, B64C 1/0009, B64C 1/06,

B64C 1/061, B64C 1/062, B64C 1/063,

B64C 1/064, B64C 1/065, B64C 1/068,

B64C 1/069, B64C 27/08, B64C 27/10,

B64C 27/20, B64C 39/00, B64C 39/001,

B64C 39/003, B64C 39/005, B64C 39/006,

B64C 39/008, B64C 39/02, B64C 39/024,

B64C 39/029 and B64U 10/00.

Group B64U 70/00 is also impacted

by reclassification into groups

<u>B64U 70/10</u>, <u>B64U 70/20</u>, <u>B64U 70/30</u>,

B64U 70/40, B64U 70/50, B64U 70/60,

B64U 70/70, B64U 70/80-B64U 70/87 and

<u>B64U 70/90</u> - <u>B64U 70/99</u>.

All groups listed in this Warning should be considered in order to perform a complete search.

70/10 • for releasing or capturing UAVs by hand

WARNING

Group <u>B64U 70/10</u> is incomplete pending reclassification of documents from groups <u>B64C 1/00</u>, <u>B64C 1/0009</u>, <u>B64C 1/06</u>, <u>B64C 1/061</u>, <u>B64C 1/062</u>, <u>B64C 1/063</u>, <u>B64C 1/064</u>, <u>B64C 1/065</u>, <u>B64C 1/068</u>, <u>B64C 1/069</u>, <u>B64C 27/08</u>, <u>B64C 27/10</u>, <u>B64C 27/20</u>, <u>B64C 39/00</u>, <u>B64C 39/001</u>, <u>B64C 39/003</u>, <u>B64C 39/005</u>, <u>B64C 39/006</u>, <u>B64C 39/008</u>, <u>B64C 39/024</u>, <u>B64C 39/029</u>, <u>B64U 10/00</u> and <u>B64U 70/00</u>. All groups listed in this Warning should be considered in order to perform a complete

considered in order to perform a complete search.

70/20 • for releasing or capturing UAVs in flight by another aircraft

WARNING

Group B64U 70/20 is incomplete pending reclassification of documents from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, B64C 1/069, B64C 27/08, B64C 27/10, B64C 27/20, B64C 39/00, B64C 39/001, B64C 39/003, B64C 39/005, B64C 39/006, B64C 39/008, B64C 39/024, B64C 39/029, B64U 10/00 and B64U 70/00.

All groups listed in this Warning should be considered in order to perform a complete search.

70/30 • for capturing UAVs in flight by ground or sea-based arresting gear, e.g. by a cable or a net

WARNING

Group B64U 70/30 is incomplete pending reclassification of documents from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, B64C 1/069, B64C 27/08, B64C 27/10, B64C 27/20, B64C 39/00, B64C 39/001, B64C 39/003, B64C 39/005, B64C 39/006, B64C 39/008, B64C 39/02, B64C 39/024, B64C 39/029, B64U 10/00 and B64U 70/00.

All groups listed in this Warning should be considered in order to perform a complete search.

70/40 • Landing characterised by flight manoeuvres, e.g. deep stall

WARNING

Group B64U 70/40 is incomplete pending reclassification of documents from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, B64C 1/069, B64C 27/08, B64C 27/10, B64C 27/20, B64C 39/00, B64C 39/001, B64C 39/003, B64C 39/005, B64C 39/006, B64C 39/008, B64C 39/02, B64C 39/024, B64C 39/029, B64U 10/00 and B64U 70/00. All groups listed in this Warning should be

All groups listed in this Warning should be considered in order to perform a complete search.

70/50 Launching from storage containers, e.g. from submarine missile tubes

WARNING

Group <u>B64U 70/50</u> is incomplete pending reclassification of documents from groups <u>B64C 1/00</u>, <u>B64C 1/0009</u>, <u>B64C 1/06</u>, <u>B64C 1/061</u>, <u>B64C 1/062</u>, <u>B64C 1/063</u>, <u>B64C 1/064</u>, <u>B64C 1/065</u>, <u>B64C 1/068</u>, <u>B64C 1/069</u>, <u>B64C 27/08</u>, <u>B64C 27/10</u>, <u>B64C 27/20</u>, <u>B64C 39/00</u>, <u>B64C 39/001</u>, <u>B64C 39/003</u>, <u>B64C 39/005</u>, <u>B64C 39/004</u>, <u>B64C 39/008</u>, <u>B64C 39/004</u>, <u>B64C 39/009</u>, <u>B64C 39/004</u>, <u>B64C 39/009</u>, <u>B64U 10/00</u> and <u>B64U 70/00</u>.

All groups listed in this Warning should be considered in order to perform a complete search.

70/60 Take-off or landing of UAVs from a runway using their own power

WARNING

Group B64U 70/60 is incomplete pending reclassification of documents from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, B64C 1/069, B64C 27/08, B64C 27/10, B64C 27/20, B64C 39/00, B64C 39/001, B64C 39/003, B64C 39/005, B64C 39/006, B64C 39/008, B64C 39/02, B64C 39/024, B64C 39/029, B64U 10/00 and B64U 70/00.

All groups listed in this Warning should be considered in order to perform a complete search.

 Launching or landing using catapults, tracks or rails (launching from storage containers <u>B64U 70/50</u>)

WARNING

70/70

Group <u>B64U 70/70</u> is incomplete pending reclassification of documents from groups <u>B64C 1/00</u>, <u>B64C 1/0009</u>, <u>B64C 1/06</u>, <u>B64C 1/061</u>, <u>B64C 1/062</u>, <u>B64C 1/063</u>, <u>B64C 1/064</u>, <u>B64C 1/065</u>, <u>B64C 1/068</u>, <u>B64C 1/069</u>, <u>B64C 27/08</u>, <u>B64C 27/10</u>, <u>B64C 27/20</u>, <u>B64C 39/00</u>, <u>B64C 39/001</u>, <u>B64C 39/003</u>, <u>B64C 39/005</u>, <u>B64C 39/004</u>, <u>B64C 39/004</u>, <u>B64C 39/029</u>, <u>B64C 39/024</u>, <u>B64C 39/029</u>, <u>B64U 10/00</u> and <u>B64U 70/00</u>. All groups listed in this Warning should be considered in order to perform a complete

considered in order to perform a complete search.

70/80 • Vertical take-off or landing, e.g. using rockets (rotorcrafts <u>B64U 10/10</u>; VTOL aircraft <u>B64U 10/20</u>)

WARNING

Group <u>B64U 70/80</u> is incomplete pending reclassification of documents from groups <u>B64C 1/00</u>, <u>B64C 1/0009</u>, <u>B64C 1/06</u>, <u>B64C 1/061</u>, <u>B64C 1/062</u>, <u>B64C 1/063</u>, <u>B64C 1/064</u>, <u>B64C 1/065</u>, <u>B64C 1/068</u>, <u>B64C 1/069</u>, <u>B64C 27/08</u>, <u>B64C 27/10</u>, <u>B64C 27/20</u>, <u>B64C 39/00</u>, <u>B64C 39/001</u>, <u>B64C 39/003</u>, <u>B64C 39/005</u>, <u>B64C 39/004</u>, <u>B64C 39/004</u>, <u>B64C 39/009</u>, <u>B64C 39/024</u>, <u>B64C 39/029</u>, <u>B64U 10/00</u> and <u>B64U 70/00</u>. Group <u>B64U 70/80</u> is also impacted by reclassification into group <u>B64U 70/83</u>. All groups listed in this Warning should be considered in order to perform a complete

70/83 . . using parachutes, balloons or the like

WARNING

Group B64U 70/83 is incomplete pending reclassification of documents from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, B64C 1/069, B64C 27/08, B64C 27/10, B64C 27/20, B64C 39/00, B64C 39/001, B64C 39/003, B64C 39/005, B64C 39/006, B64C 39/008, B64C 39/024, B64C 39/029, B64U 10/00, B64U 70/00 and B64U 70/80.

All groups listed in this Warning should be considered in order to perform a complete search.

70/87 . . using inflatable cushions

WARNING

Group B64U 70/87 is incomplete pending reclassification of documents from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, $\underline{B64C\ 1/069}, \underline{B64C\ 27/08}, \underline{B64C\ 27/10},$ B64C 27/20, B64C 39/00, B64C 39/001, B64C 39/003, B64C 39/005, B64C 39/006, B64C 39/008, B64C 39/02, B64C 39/024, B64C 39/029, B64U 10/00 and B64U 70/00. All groups listed in this Warning should be considered in order to perform a complete

70/90 . Launching from or landing on platforms

WARNING

search.

Groups B64U 70/90 - B64U 70/99 are incomplete pending reclassification of documents from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, B64C 1/069, B64C 27/08, B64C 27/10, B64C 27/20, B64C 39/00, B64C 39/001, B64C 39/003, B64C 39/005, B64C 39/006, B64C 39/008, B64C 39/02, B64C 39/024, B64C 39/029, B64U 10/00 and B64U 70/00.

All groups listed in this Warning should be considered in order to perform a complete search.

70/92 . . Portable platforms

70/97

70/93 . . . for use on a land or nautical vehicle

70/95 . . Means for guiding the landing UAV towards the platform, e.g. lighting means

> . . Means for guiding the UAV to a specific location on the platform, e.g. platform structures

preventing landing off-centre

70/99 Means for retaining the UAV on the platform, e.g. dogs or magnets

80/00 Transport or storage specially adapted for UAVs

WARNING

Group B64U 80/00 is incomplete pending reclassification of documents from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, B64C 1/069, B64C 27/08, B64C 27/10, B64C 27/20, B64C 39/00, B64C 39/001, B64C 39/003, B64C 39/005, B64C 39/006, B64C 39/008, B64C 39/02, B64C 39/024, B64C 39/029 and B64U 10/00.

Group B64U 80/00 is also impacted by reclassification into groups B64U 80/10, B64U 80/20-B64U 80/25, B64U 80/30, B64U 80/40, B64U 80/50, B64U 80/60, B64U 80/70 and B64U 80/80-B64U 80/86.

All groups listed in this Warning should be considered in order to perform a complete search. 80/10 . with means for moving the UAV to a supply or launch location, e.g. robotic arms or carousels

WARNING

Group B64U 80/10 is incomplete pending reclassification of documents from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, B64C 1/069, B64C 27/08, B64C 27/10, B64C 27/20, B64C 39/00, B64C 39/001, B64C 39/003, B64C 39/005, B64C 39/006, B64C 39/008, B64C 39/02, B64C 39/024, B64C 39/029, B64U 10/00 and B64U 80/00. All groups listed in this Warning should be considered in order to perform a complete

80/20 . with arrangements for servicing the UAV

WARNING

Groups B64U 80/20 and B64U 80/25 are incomplete pending reclassification of documents from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, B64C 1/069, B64C 27/08, B64C 27/10, B64C 27/20, B64C 39/00, B64C 39/001, B64C 39/003, B64C 39/005, B64C 39/006, B64C 39/008, B64C 39/02, B64C 39/024, B64C 39/029, B64U 10/00 and B64U 80/00.

All groups listed in this Warning should be considered in order to perform a complete search.

. . for recharging batteries; for refuelling

. with arrangements for data transmission

WARNING

80/25

80/30

Group B64U 80/30 is incomplete pending reclassification of documents from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, B64C 1/069, B64C 27/08, B64C 27/10, B64C 27/20, B64C 39/00, B64C 39/001, B64C 39/003, B64C 39/005, B64C 39/006, B64C 39/008, B64C 39/02, B64C 39/024, B64C 39/029, B64U 10/00 and B64U 80/00.

All groups listed in this Warning should be considered in order to perform a complete search.

80/40 . for two or more UAVs

WARNING

Group B64U 80/40 is incomplete pending reclassification of documents from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, B64C 1/069, B64C 27/08, B64C 27/10, B64C 27/20, B64C 39/00, B64C 39/001, B64C 39/003, B64C 39/005, B64C 39/006, B64C 39/008, B64C 39/024, B64C 39/029, B64U 10/00 and B64U 80/00.

All groups listed in this Warning should be considered in order to perform a complete search.

. the UAVs being disassembled

WARNING

Group B64U 80/50 is incomplete pending reclassification of documents from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, B64C 1/069, B64C 27/08, B64C 27/10, B64C 27/20, B64C 39/00, B64C 39/001, B64C 39/003, B64C 39/005, B64C 39/006, B64C 39/008, B64C 39/024, B64C 39/029, B64U 10/00 and B64U 80/00.

All groups listed in this Warning should be considered in order to perform a complete search.

80/60 . by wearable objects, e.g. garments or helmets

WARNING

Group B64U 80/60 is incomplete pending reclassification of documents from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, B64C 1/069, B64C 27/08, B64C 27/10, B64C 27/20, B64C 39/00, B64C 39/001, B64C 39/003, B64C 39/005, B64C 39/006, B64C 39/008, B64C 39/024, B64C 39/029, B64U 10/00 and B64U 80/00.

All groups listed in this Warning should be considered in order to perform a complete search.

• in containers (<u>B64U 80/60</u> takes precedence)

WARNING

Group <u>B64U 80/70</u> is incomplete pending reclassification of documents from groups <u>B64C 1/00</u>, <u>B64C 1/0009</u>, <u>B64C 1/06</u>, <u>B64C 1/061</u>, <u>B64C 1/062</u>, <u>B64C 1/063</u>, <u>B64C 1/064</u>, <u>B64C 1/065</u>, <u>B64C 1/068</u>, <u>B64C 1/069</u>, <u>B64C 27/08</u>, <u>B64C 27/10</u>, <u>B64C 27/20</u>, <u>B64C 39/00</u>, <u>B64C 39/001</u>, <u>B64C 39/003</u>, <u>B64C 39/005</u>, <u>B64C 39/004</u>, <u>B64C 39/008</u>, <u>B64C 39/024</u>, <u>B64C 39/029</u>, <u>B64U 10/00</u> and <u>B64U 80/00</u>. All groups listed in this Warning should be

All groups listed in this Warning should be considered in order to perform a complete search.

80/80 . by vehicles

WARNING

Groups B64U 80/80 - B64U 80/86 are incomplete pending reclassification of documents from groups B64C 1/00, B64C 1/0009, B64C 1/06, B64C 1/061, B64C 1/062, B64C 1/063, B64C 1/064, B64C 1/065, B64C 1/068, B64C 1/069, B64C 27/08, B64C 27/10, B64C 27/20, B64C 39/00, B64C 39/001, B64C 39/003, B64C 39/005, B64C 39/006, B64C 39/008, B64C 39/02, B64C 39/024, B64C 39/029, B64U 10/00 and B64U 80/00.

All groups listed in this Warning should be considered in order to perform a complete search.

80/82 . . Airborne vehicles80/84 . . Waterborne vehicles80/86 . . Land vehicles

Indexing scheme associated with groups B64U 10/00 - B64U 80/00

2101/00 UAVs specially adapted for particular uses or applications

WARNING

Group B64U 2101/00 is impacted by reclassification into groups B64U 2101/05, B64U 2101/10, B64U 2101/15 - B64U 2101/19, B64U 2101/20 - B64U 2101/24, B64U 2101/25 - B64U 2101/29, B64U 2101/30 - B64U 2101/32, B64U 2101/30, B64U 2101/45 - B64U 2101/47, B64U 2101/55 - B64U 2101/58, B64U 2101/60 - B64U 2101/69, B64U 2101/70

and <u>B64U 2101/75</u>.
All groups listed in this Warning should be considered in order to perform a complete search.

• for sports or gaming, e.g. drone racing

WARNING

Group <u>B64U 2101/05</u> is incomplete pending reclassification of documents from group <u>B64U 2101/00</u>.

Groups <u>B64U 2101/00</u> and <u>B64U 2101/05</u> should be considered in order to perform a complete search.

• for generating power to be supplied to a remote station, e.g. UAVs with solar panels

WARNING

Group B64U 2101/10 is incomplete pending reclassification of documents from group B64U 2101/00.

Groups $\underline{B64U\ 2101/00}$ and $\underline{B64U\ 2101/10}$ should be considered in order to perform a complete search.

2101/15 • for conventional or electronic warfare

WARNING

Group B64U 2101/15 is incomplete pending reclassification of documents from group B64U 2101/00.

Group B64U 2101/15 is also impacted by reclassification into groups B64U 2101/16, B64U 2101/17, B64U 2101/18 and B64U 2101/19.

All groups listed in this Warning should be considered in order to perform a complete

2101/16 . . for controlling, capturing or immobilising other vehicles

WARNING

Group B64U 2101/16 is incomplete pending reclassification of documents from groups B64U 2101/00 and B64U 2101/15.

Groups B64U 2101/00, B64U 2101/15 and B64U 2101/16 should be considered in order to perform a complete search.

2101/17 . . for detecting, disrupting or countering communications

WARNING

Group <u>B64U 2101/17</u> is incomplete pending reclassification of documents from groups B64U 2101/00 and B64U 2101/15.

Groups B64U 2101/00, B64U 2101/15 and B64U 2101/17 should be considered in order to perform a complete search.

2101/18 . . for dropping bombs; for firing ammunition

WARNING

Group <u>B64U 2101/18</u> is incomplete pending reclassification of documents from groups B64U 2101/00 and B64U 2101/15.

Groups B64U 2101/00, B64U 2101/15 and B64U 2101/18 should be considered in order to perform a complete search.

2101/19 . . for use as targets or decoys

WARNING

Group <u>B64U 2101/19</u> is incomplete pending reclassification of documents from groups B64U 2101/00 and B64U 2101/15.

Groups B64U 2101/00, B64U 2101/15 and B64U 2101/19 should be considered in order to perform a complete search.

• for use as communications relays, e.g. high-altitude platforms

WARNING

Group B64U 2101/20 is incomplete pending reclassification of documents from group B64U 2101/00.

Group B64U 2101/20 is also impacted by reclassification into groups B64U 2101/21, B64U 2101/23 and B64U 2101/24.

All groups listed in this Warning should be considered in order to perform a complete search.

2101/21 . . for providing Internet access

WARNING

Group B64U 2101/21 is incomplete pending reclassification of documents from groups B64U 2101/00 and B64U 2101/20.

Groups B64U 2101/00, B64U 2101/20 and B64U 2101/21 should be considered in order to perform a complete search.

2101/23 . . for providing telephone services

WARNING

Group B64U 2101/23 is incomplete pending reclassification of documents from groups B64U 2101/00 and B64U 2101/20.

Groups B64U 2101/00, B64U 2101/20 and B64U 2101/23 should be considered in order to perform a complete search.

2101/24 . . for use as flying displays, e.g. advertising or billboards

WARNING

Group B64U 2101/24 is incomplete pending reclassification of documents from groups B64U 2101/00 and B64U 2101/20.

Groups B64U 2101/00, B64U 2101/20 and B64U 2101/24 should be considered in order to perform a complete search.

2101/25 • for manufacturing or servicing

WARNING

Groups B64U 2101/25 - B64U 2101/29 are incomplete pending reclassification of documents from group B64U 2101/00.

All groups listed in this Warning should be considered in order to perform a complete search.

2101/26 . . for manufacturing, inspections or repairs

2101/28 . . for painting or marking

2101/29 . . for cleaning

2101/30 • for imaging, photography or videography

WARNING

Group <u>B64U 2101/30</u> is incomplete pending reclassification of documents from group <u>B64U 2101/00</u>.

Group $\underline{B64U\ 2101/30}$ is also impacted by reclassification into groups $\underline{B64U\ 2101/31}$ and $\underline{B64U\ 2101/32}$.

All groups listed in this Warning should be considered in order to perform a complete search.

2101/31 . . for surveillance

WARNING

Group <u>B64U 2101/31</u> is incomplete pending reclassification of documents from groups <u>B64U 2101/00</u> and <u>B64U 2101/30</u>.

Groups B64U 2101/00, B64U 2101/30 and B64U 2101/31 should be considered in order to perform a complete search.

2101/32 . . for cartography or topography

WARNING

Group <u>B64U 2101/32</u> is incomplete pending reclassification of documents from groups <u>B64U 2101/00</u> and <u>B64U 2101/30</u>.

Groups $\underline{B64U\ 2101/00}$, $\underline{B64U\ 2101/30}$ and $\underline{B64U\ 2101/32}$ should be considered in order to perform a complete search.

2101/35 • for science, e.g. meteorology

WARNING

Group <u>B64U 2101/35</u> is incomplete pending reclassification of documents from group <u>B64U 2101/00</u>.

Groups <u>B64U 2101/00</u> and <u>B64U 2101/35</u> should be considered in order to perform a complete search.

• for agriculture or forestry operations

WARNING

Group <u>B64U 2101/40</u> is incomplete pending reclassification of documents from group <u>B64U 2101/00</u>.

Groups <u>B64U 2101/00</u> and <u>B64U 2101/40</u> should be considered in order to perform a complete search.

 for releasing liquids or powders in-flight, e.g. cropdusting

WARNING

Groups $\underline{B64U\ 2101/45}$ and $\underline{B64U\ 2101/47}$ are incomplete pending reclassification of documents from group $\underline{B64U\ 2101/00}$.

Groups <u>B64U 2101/00</u>, <u>B64U 2101/45</u> and <u>B64U 2101/47</u> should be considered in order to perform a complete search.

2101/47 . . for fire fighting

• for life-saving or rescue operations; for medical use

WARNING

Groups <u>B64U 2101/55</u> - <u>B64U 2101/58</u> are incomplete pending reclassification of documents from group <u>B64U 2101/00</u>.

All groups listed in this Warning should be considered in order to perform a complete search.

2101/56 . . for locating missing persons or animals

2101/57 . . for bringing emergency supplies to persons or animals in danger, e.g. ropes or life vests

2101/58 • for medical evacuation, i.e. the transportation of persons or animals to a place where they can receive medical care

2101/60 • for transporting passengers; for transporting goods other than weapons

WARNING

Group <u>B64U 2101/60</u> is incomplete pending reclassification of documents from group <u>B64U 2101/00</u>.

Group <u>B64U 2101/60</u> is also impacted by reclassification into groups <u>B64U 2101/61</u>, <u>B64U 2101/64-B64U 2101/66</u>, <u>B64U 2101/67</u> and <u>B64U 2101/69</u>.

All groups listed in this Warning should be considered in order to perform a complete search.

2101/61 . . for transporting passengers

WARNING

Group $\underline{B64U\ 2101/61}$ is incomplete pending reclassification of documents from groups $\underline{B64U\ 2101/00}$ and $\underline{B64U\ 2101/60}$.

Groups <u>B64U 2101/00</u>, <u>B64U 2101/60</u> and <u>B64U 2101/61</u> should be considered in order to perform a complete search.

2101/64 . . for parcel delivery or retrieval

WARNING

Groups <u>B64U 2101/64</u> and <u>B64U 2101/66</u> are incomplete pending reclassification of documents from groups <u>B64U 2101/00</u> and <u>B64U 2101/60</u>.

All groups listed in this Warning should be considered in order to perform a complete search.

2101/66 . . . for retrieving parcels

2101/67 . the UAVs comprising tethers for lowering the goods

WARNING

Group <u>B64U 2101/67</u> is incomplete pending reclassification of documents from groups <u>B64U 2101/00</u> and <u>B64U 2101/60</u>.

Groups $\underline{B64U\ 2101/00}$, $\underline{B64U\ 2101/60}$ and $\underline{B64U\ 2101/67}$ should be considered in order to perform a complete search.

2101/69 . . the UAVs provided with means for airdropping goods, e.g. deploying a parachute during descent

WARNING

Group B64U 2101/69 is incomplete pending reclassification of documents from groups B64U 2101/00 and B64U 2101/60.

Groups B64U 2101/00, B64U 2101/60 and B64U 2101/69 should be considered in order to perform a complete search.

• for use inside enclosed spaces, e.g. in buildings or in vehicles

WARNING

Group <u>B64U 2101/70</u> is incomplete pending reclassification of documents from group B64U 2101/00.

Groups $\underline{B64U\ 2101/00}$ and $\underline{B64U\ 2101/70}$ should be considered in order to perform a complete search.

• for extra-terrestrial use, e.g. on the Moon or Mars

WARNING

Group B64U 2101/75 is incomplete pending reclassification of documents from group B64U 2101/00.

Groups $\underline{B64U\ 2101/00}$ and $\underline{B64U\ 2101/75}$ should be considered in order to perform a complete search.

2201/00	UAVs characterised by their flight controls
2201/10	autonomous, i.e. by navigating independently
	from ground or air stations, e.g. by using inertial
	navigation systems [INS]
2201/102	• adapted for flying in formations
2201/104	using satellite radio beacon positioning systems,
	e.g. GPS
2201/20	Remote controls
2201/202	• using tethers for connecting to ground station