Tabelle 1

Steuerreihenfolge Getriebe Steuerung Up													
Gang	Schritt 1	Verzögerung	Schritt 2	Verzögerung	Schritt 3	Verzögerung	Schritt 4	Verzögerung	Schritt 5	Verzögerung	Schritt 6	Verzögerung	Schritt 7
R	MB 3.1 +												
N	MB 3.1 +		MB 2.1 +		MB 2.3 +		MB 1.1 +		MB 1.3 +		MB 3.1 -		
1	MB 3.1 +		MB 2.1 -		MB 1.1 -		MB 3.1 -						
2	MB 3.1 +		MB 1.3 -		MB 1.1 +		MB 1.2 +		MB 3.1 -				
3	MB 3.1 +		MB 1.3 +		MB 1.2 -		MB 2.3 -		MB 2.1 +		MB 2.3 +		MB 3.1 -
4	MB 3.1 +		MB 1.3 -		MB 1.2 +		MB 1.1 +		MB 3.1 -				
5	MB 3.1 +		MB 1.3 +		MB 1.2 -		MB 1.1 -		MB 3.1 -				