	Advantages	Disadvantages
Atwood Machine	+ Easy calculation	+ Easy calculation
Pendulum	+ Easy to implement	- Two designs needed
Springs	rcalculation +Easy do d	- Characteristics of spring unknown

	Advantages	Disadvantages
Atwood Machine	+ Easy calculation	- Preperation of setup takes long because of falling mass- (Controllable motor needed)
Pendulum	+ Simple design	- Different designs depending on axis
Springs	+Easy calculation +Simple design	- Spring characteristics have to be determined