

Introduction to Mechanical Engineering, HW CAD REN 1Render

IMODOLIZ

Short Task Description

Description: Make a static picture and kinematics render of the assembly

Artifacts: Zip archive with NX details files (.prt) + rendered picture (.png) (resolution — min 2K) + rendered video (.avi or .mp4)

Extended Task Description

Input files: the resulting assembly from HWs/HW_CAD_ASM2. If you have not added a robot leg, do it.

- 1. **Assign materials and colors** for each component of assembly based on your own sense of beauty.
- 2. Choose some scene and **render a photorealistic scene**. Try to reduce noise as much as possible. Make a minimal picture resolution 2K.
- Make a scene in Animation Designer and based on it make a rendered video. It will
 take a long time to calculate, so either be prepared to wait, or choose not realistic
 settings.

