## SMART AUTHENTICATION ID REGISTRATION PROCEDURE

- Each Honda SMART Key has its particular ID number that cannot be changed or deleted.
- The Honda SMART Key that was registered once in the smart control unit cannot be registered in another smart control unit.

## **COMMUNICATION ERRORS INSPECTION**

- To register the smart authentication ID, use a radio communication. Before registration, check the below items that may cause communication error.
  - A TV tower, power generation plant, broadcast station, airport or other facility that generates strong radio wave or noise is not situated nearby.
  - The Honda SMART Key is not brought together with a wireless communications device such as wireless applications and mobile phone or laptop.
  - The Honda SMART Key does not make contact with or is not covered by a metallic product.
  - The vehicle battery voltage is not low
  - The Honda SMART Key battery power is not low
  - The Honda SMART Key does not have any trouble
  - The smart control unit does not have any trouble
  - The associated circuits of the smart control unit do not have any trouble

## SMART AUTHENTICATION DIAGNOSTIC CODE

If the smart authentication ID is registered and not completed normally, the following error codes appear.

Honda SMART Key indicator blinking pattern	Symptom	Remedy
ON OFF	Communication error between the Honda SMART Key and smart control unit	Check for any communication error.
ON OFF	Failure to register the Honda SMART Key	Perform the Honda SMART Key registration procedure again.
ON OFF	The Honda SMART Key has already registered.	Check the behavior with the previously registered Honda SMART Key.
ON OFF	The Honda SMART Key has already registered in other vehicle.	Use a new Honda SMART Key to perform the registration procedure again.