Quarterly Maintenance Manual

The coolant pump on unit B7 must be replaced every 4000 operating hours. Torque the housing bolts to 45 Nm in a star pattern.