
SWAT-CUP

Automated model calibration requires that the uncertain model parameters are systematically changed, the model is run, and the required outputs (corresponding to measured data) are extracted from the model output files. The main function of an interface is to provide a link between the input/output of a calibration program and the model. The simplest way of handling the file exchange is through text file formats.

SWAT-CUP is an interface that was developed for SWAT. Using this generic interface, any calibration/uncertainty or sensitivity program can easily be linked to SWAT. A schematic of the linkage between SWAT and five optimization programs is illustrated in the Figure below.



Step-by-step Creating of SWAT-SUFI2 Input Files

