




Note: The HY-TTC 5xx and 2000 ECU family has a wake-up pin in addition to K15. The ECU starts with a wake-up pin high similar to a K15 high. If K15 is not high prior to the wake-up pin delay, the ECU will shut down without executing the shutdown phase.