Vivado synthesis is experiencing difficulties due to a crash in the HARTHOptPost::prepDsps()function.

Hello,

I'm experiencing a crashing issue with Vivado while synthesizing design files. My system runs on Linux, and I'm using Vivado version 2024.1. The relevant commands I'm using in the Ubuntu terminal are as follows:

vivado -mode tcl
read_verilog design.v
synth design -top top -flatten hierarchy none -bufg 5 -directive AreaMapLargeShiftRegToBRAM

During the synthesis process, there's a crash, and a log is generated with information about the cause of the crash.

Please check '/home/user/vivado_project/hs_err_pid1229857.log' for details segfault in /home/user/software/vivado2024/Vivado/2024.1/bin/unwrapped/lnx64.o/v ivado -exec vivado -mode tcl, exiting...

user@user-System-Product-Name:~/vivado_project\$ Parent process (pid 1229857) has died. This helper process will now exit