```
Code (Light Sensor):
#include "grove.h" //for light->name(), light->value()
#include <stdio.h> // for printf()
#include <unistd.h> //for sleep()
int main()
{
        // Create the light sensor object using AIO pin 0
              upm::GroveLight* light = new upm::GroveLight(0);
              // Read the input and print both the raw value and a rough lux value,
              // waiting one second between readings
              for (int i=20;i>0;i--) {
                     printf(" Light value is %f which is roughly %d lux \n", light-
>raw_value(), light->value());
                     fflush(stdout);
                     sleep(1);
              }
              // Delete the light sensor object
              printf("Exiting .. bbye!");
              delete light;
}
```