

Incident Report - INC-4018

Type: Fire

Location: Zone A

Date: 2025-05-04

Severity: Medium

Description:

On 2025-05-04, at around 07:31:02, a fire erupted in a residential/commercial area in Zone A. Initial reports suggest that the cause was likely an electrical short circuit or a flammable substance catching fire. Thick smoke was visible from nearby blocks, and residents immediately reported the incident to local authorities. Multiple housing units were evacuated as a precautionary measure, and emergency services were dispatched promptly.

Action Taken:

The Fire and Rescue Department responded within minutes and deployed multiple fire trucks to the site. The fire was brought under control in approximately two hours. Firefighters ensured no casualties occurred. Authorities temporarily cut power supply to the area, and safety checks were initiated for surrounding buildings. A full inspection and audit of fire safety measures has been scheduled.