


AMSB with noise checking procedure

STEP1: Please refer to the below video link to remove the main cover :

<https://www.dropbox.com/s/17raf8zw6glms06/How%20to%20remove%20the%20AMSB%20main%20cover%20and%20fan.avi?dl=0>



Unscrew 4x Screws



Disconnect the M2 VR cable



Remove the main cover




STEP 2: Please help to check if the E2 Clip is missing from the location circled in yellow as below?

1- If E2 falls off and not at its place, then please put the #E2 Clip back to his original place.

2- If E2 is missing, then please replace to a new E2 Clip then can fix the issue.

Note: Sometimes the missing E2 will stuck to the inside of face of the E12 ring magnet as **picture 1**.



STEP 3: Please also help to remove the fan to Check if any parts interfere or rub with each other? Could you please take pictures on any frictional parts?

Video link for how to remove the main cover and fan:

<https://www.dropbox.com/s/dqgxre6h473kmgo/How%20to%20remove%20the%20AMSB%20main%20cover%20and%20fan.avi?dl=0>

