OIL-FREE SLIDE PLATES


—COPPER ALLOY 20mm TYPE・2 BOLT HOLES / 4 BOLT HOLES—

—2 bolt holes—

RoHS

SEW W= 28 ～ 75


SEWT W=100 ～ 150




—4 bolt holes—

RoHS

SEW W=100 ～ 150





※For W=28 or 38, the R in the longer direction is R2.

- Slide direction
  For W=28 or 38, slide direction is the longer direction (L) only.
- The use of initial break-in greasing will make the product more effective.

Ⓜ Copper alloy
Special solid lubricant (embedded)

ℓ	Catalog No.	W	L
45	— 2 bolt holes — SEW	28	75
50			100
100			150
45		38	75
50			100
100			150
45		48	75
50			100
75			125
100			150
150			200
45		58	75
50			100
100			150
25		75	75
50			100
75			125
100			150
150			200
50	— 2 bolt holes — SEWT	100	100
75			125
100			150
150			200
200			250
200			300
75		125	125
100			150
150			200
200			250
200			300
200			350
100		150	150
150			200
200			250

ℓ	ℓ1	Catalog No.	W	L
50	50	— 4 bolt holes — SEW	100	100
75				125
100				150
150				200
200				250
200				300
75	50		125	125
100				150
150				200
200				250
200				300
200				350
100	100		150	150
150				200
200				250

Order

Catalog No.	W	—	L
SEW	75	—	125
SEWT	150	—	200

Days to Ship Quotation

Price Quotation

■Shims for oil-free slide plates P.1142