

Sustainer
Booster
Quarter step minus primary T_s [K]
40
20
0
−20
−40
−60
0
1
2
3
4
5
6
7
Time since heating starts [s]
Time since heating starts [s]
Al
CF
Al
CF