
Nylon screws
Aluminium screws
Base X
Base Y
Base Z
6.4
15.5
9.7
24.5
7.7
11.5
3.1
8.9
7.2
11.2
5.6
9.4
0
5
10
15
20
25
Time from start of excitation [ms]
First spacer opens or closes
Middle pocket loses net compression