

PLA across layers
PLA in print plane
M4 screw shank
Peak / coupon mean [%]
Peak longitudinal tension [MPa]
Base excitation axis
X
Y
Z
52
116
77
133
62
208
38
76
38
71
38
115
31
96
36
71
35
94
Nylon screws
Aluminium screws