

Across layers (40.5 MPa)
In the print plane (52.3 MPa)
Maximum in the startup ramp [MPa]
0
20
40
60
80
100
Base X
Base Y
Base Z
Base X
Base Y
Base Z
Nylon screws
Aluminium screws
At least 2 mm from bearing nodes