Procedure - epoxy coat
Ensure all nastiness sanded
O obtain lint-free wipe
O follow cleaning instructions on blue bottle
wipe carefully
O prepare epoxy - let sit for 40 (possibly 50) min to be *gooooppyyy* (more viscous)
O paint 1 layer
O wait for dry
O paint 2 layer
O wait for dry