
NOTIFICATION / BUTTON

For this type of sensor it is recommended to use a breadboard adapter as in the image below. <u>Careful! Power supply to 3.3V DC.</u> Regardless of the type of application you want, closing the circuit between GND and GP2 will signal this action.



As a model...

In order to have 3.3V DC a DC-DC step down power supply module is recommended.



As a model...

And power supply can be done with a transformer from 230V / 110V AC to 5V DC



