

## TEMPERATURE & HUMIDITY

1. In order to be fully functional, it is necessary to bridge between the pins marked in the images below.



## 2. Power supply will be with 5V DC.



## As a model...

And power supply can be done with a transformer from 230V / 110V AC to 5V DC

