readme.md 2024-09-18

Verification Plan for Sequential ALU

You Can find the Simulation Here: Simulation at EDAplayground

1. Inputs and Outputs

• Inputs:

- o clk: Clock signal for sequential operation.
- o rst: Reset signal to initialize the ALU.
- o opcode: Control signal to select the operation (e.g., addition, subtraction).
- A, B: Operands for the ALU.

Outputs:

• Result: Output result of the ALU operation.

2. Test Plan

2.1 Test Scenarios

1. Reset Condition:

• Ensure the ALU resets to 0 when the reset signal is high.

2. Addition Operation:

- \circ Verify the correctness of the addition operation (A + B).
- Test edge cases, such as when A or B are 0, FF, and overflow conditions.

3. Subtraction Operation:

- Test A B for different operand values.
- Check underflow conditions (i.e., A < B).

4. AND Operation:

• Test A & B for different values of A and B.

5. **OR Operation:**

• Test A | B for different values of A and B.

6. XOR Operation:

Test A ^ B for different operand values.

7. Sequential Execution:

Verify the ALU executes operations sequentially in each clock cycle.

2.2 Corner Cases

readme.md 2024-09-18

- Test when A and B are both zero.
- Test operations with maximum and minimum possible values for operands.
- Verify behavior when an undefined opcode is provided.

3. Pass/Fail Criteria

The test will be considered pass if:

- The ALU performs all operations correctly as per the opcode.
- Functional coverage shows 100% for all scenarios.
- There are no assertion failures during the simulation.

The test will be considered **fail** if any of the following conditions occur:

- Incorrect ALU results for valid operations.
- The ALU does not reset correctly or fails to respond to the clock signal.