```
%Generate angle data for GSE FSM for PAT Test Dithering
test period sec = 900;
dither_frequency_hz = 1;
boundary_rad = 3*(122.1730476 * 1e-6); %3 sigma bus pointing error
 from Pointing_Budget_V4.0.xlsx
filename = ['pat_cmds_', num2str(dither_frequency_hz), 'hz_',
 num2str(test_period_sec),'sec.csv'];
dither_per_sec_sigma_rad = deg2rad(0.0183)/(3*10);
number_pts = test_period_sec*dither_frequency_hz;
dither_sigma_rad = dither_per_sec_sigma_rad/dither_frequency_hz;
sig_figs = 6; %step resolution is about 1e-6 rad
angles rel rad = zeros(number pts, 2);
angles_rad = zeros(number_pts, 2);
angles_rad(1,:) = [0,0];
angles_rel_rad(1,1) = round(normrnd(0,dither_sigma_rad), 6);
angles_rel_rad(1,2) = round(normrnd(0,dither_sigma_rad), 6);
for i = 2:number_pts
    if(norm(angles_rad(i-1,:)) >= boundary_rad)
        mu_dither = -3*dither_sigma_rad; %catch it from going out of
 bounds
    else
        mu_dither = 0;
    end
    for j = 1:2
        angles_rel_rad(i,j) =
 round(normrnd(sign(angles_rad(i-1,j))*mu_dither,dither_sigma_rad),
 6); %standard gaussian update
        angles_rad(i,j) = angles_rad(i-1,j) + angles_rel_rad(i,j);
    end
end
angles_rad = [angles_rad; [0,0]];
angles_rel_rad = [angles_rel_rad; angles_rad(end,:) -
 angles_rad(end-1,:)];
number pts = number pts + 1;
TIME = linspace(0,test_period_sec,number_pts)';
X_CMD = angles_rel_rad(:,1);
Y_CMD = angles_rel_rad(:,2);
T = table(X CMD, Y CMD);
writetable(T,filename);
figure;
plot(angles_rad(:,1)*1e3, angles_rad(:,2)*1e3,'*');
hold on;
plot(angles_rad(end,1)*1e3, angles_rad(end,2)*1e3,'ro');
xlabel('X (mrad)');
ylabel('Y (mrad)');
title('GSE FSM Angles for PAT Dither');
hold off;
figure;
subplot(1,2,1);
```

```
histogram(1e3*angles_rad(:,1));
xlabel('X (mrad)');
title(['3\sigma_x (mrad) = ', num2str(3*std(angles_rad(:,1)))]);
subplot(1,2,2);
histogram(1e3*angles_rad(:,2));
xlabel('Y (mrad)');
title(['3\sigma_y (mrad) = ', num2str(3*std(angles_rad(:,2)))]);
figure;
subplot(2,1,1);
plot(TIME, angles_rel_rad(:,1)*1e3,'*');
ylabel('X_CMDS (mrad)');
title('GSE FSM Relative Angles for PAT Dither in Each Axis');
subplot(2,1,2);
plot(TIME, angles_rel_rad(:,2)*1e3,'*');
ylabel('Y_CMDS (mrad)');
xlabel('TIME (sec)');
```





