Review input, stale, output, error strucks and basic flow in main	8 hr
(correct if necessary) Review startup/init procedures w/ team and correct code init.c if necessary Review 2-updates debug interface code + DEBUG LEDS	16 hr
Review shutdown procedures and review code in shutdown normal c	8 hr
[] Review & correct charge and park	8 hr
[] (reale DRIVE.C	8 hr
After init/park/charge/drive/n_shutdown done, discuss u/ team errors we'll produce - implement SHUTDOWN_ERROR.C SM	t Correct responses 16 hr

I Investigate + purchase key HW

LPC's

D Build circuit to feel key voltage > PIO

12 hr

D Write code to delect change in PIO

12 hr

X 2 for car R/P/F stick lever