\* What did you do? 1 Shutdown \* Shutdown Sequence

\* What will you do

\* Documentation (Skanda) ver Request off

\* Blugging \* Expenses (Range & Eric) while off condition) Change h.b. to shutdown. off conditions while (modules shutting down) {? open contactor-(h.b.=0ff VC == 0 while (contactors closed) {} modules w shutdown stuff open c.s. relay MI (just MC) UI (just Pi) open I.v. relay