

Item No.	Description	Part # (if applicable)	Qty	Unit Price (₹)	Total Cost (₹)
PARTS					
P1	Rear Bumper Cover	71501-TBA-A00	1	12,000.00	12,000.00
P2	Bumper Mounting	ASSY-890	1	800	800
P3	Misc. Fasteners/Bolts	-	1	250	250
LABOR					
L1	R&I (Remove & Install)	-	2	750	1,500.00
L2	Repair Rear Right Fender	-	1	1,200.00	1,200.00
L3	Paint & Refinish	-	3	850	2,550.00
L4	Paint & Refinish	-	2	850	1,700.00
MATERIALS					
M1	Paint Materials (Primer, Base Coat)	-	1	1,800.00	1,800.00
M2	Shop Supplies (Sandpaper, Masking Tape)	-	1	500	500

Notes		
Required replacement		
Replace as per standard procedure		
2 hours @ ₹750/hour		
Light PDR/body work		
Includes priming, basecoat, clearcoat		
Blending required		
Per standard paint material charges		
Standard charge for consumables		