Troubleshooting: DCU1_a000_tluCurrentLow - VH6.B3/B4

This procedure explains how to troubleshoot this Door Control Unit (DCU) diagnostic fault DCU1_a000_tluCurrentLow, when 1x top DOOR LATCH, UPR ASM (P00003764-01-AA) current is low.

Fault Description


BaseOps Fault ID	Supplier Fault ID	Fault Name	Fault Description
03D09E	a000	DCU1_a000_tluCurrentLow	1x DOOR LATCH, UPR ASM current is low.

Reference

Source	Severity	
DCU1	Alert	

Circuit/System Description: The door latch consist of a DC motor and 5 switches. It electrically releases and cinches via a single motor/lever output.

Wiring Diagram: DCU1



Electrical Component Connector Pinout: N/A

Special Tools

Tool Name

N/A

Setting Criteria

- 1. Cinch/Release Motors, Current is (<0.1A.).
- 2. Set Debouncing Time is 500ms.

Clearing Criteria

Note: DCU Mode State Requires Another 10s to Transition From 'Fault' to 'Operation' State.

After the First trigger DCU1_a000_tluCurrentLow Self-Clears in 500ms.

Failsoft Actions

1x DCU goes to Faulted Mode.

Diagnostic Procedure

- 1. Verify the Following for DCU1_a000_tluCurrentLow:
 - a. No other faults in 1xDCU1.
 - b. **CAN Signal DCU1_tluLastTransition** is requested.

Firefly User Manual - VH6 Fleet-Wide

- 2. Inspect 1x Latch, Door Asm Circuit and Verify there is NO:
 - Burnt/melted plastic
 - Damaged Terminal Pins
 - Loose connectors
 - Recessed Terminal Pins
- 3. **Note:** Always Disconnect Harness, Asm Connectors When Resistance is Measured.

Measure the Circuit Resistance for 1x **Door Latch**, **Upr Asm**:

Table 1. DCU1

Latch, Door, CDI	₹	То	DCU CDR
(R015), Pin 4	То		(B906), Pin K2
(R015), Pin 7	То		(B907), Pin F3
(R015), Pin 8	То		(B907), Pin F1

- 4. If the Resistance is:
 - o (>0 Ohms), Repair 1x Harness, Body Asm and or 1x Harness, Roof Asm
 - o (O Ohms), Replace 1x Latch, Door Asm (P00003764-01-AA)

Replacement: Door Latch, Upper, Angled (P00003765-01) - VH6.B3

Remove/Replace Procedure Links

Procedures

Firefly User Manual - VH6 Fleet-Wide

Replacement: Door Latch, Upper, Angled (P00003765-01) - VH6.B3

Repair Verification Steps

The Doors Release and Open and the Doors Close and Cinch.

Revision History

Version	Description	JIRA	Date
1	Initial release.	BD-1669	November 15, 2024