

N0 G21 G40 G54 G90 G95 ; N80 G00 X81 Z2 ;

N1 G28 U0 W0 ; N85 G41 ;

N2 T0101 M08; N90 G70 P45 Q55 F0.2;

N3 G50 S3000 ; N95 X81 ;

N4 G96 S300 M03; N100 G00 X100 Z100 T00;

N5 G00 X0 Z-0.5; N105 T0505;

N6 G00 X85; N110 G01 X81 Z-21.5 F0.08;

N10 G01 Z0 F0.2; N115 G01 X60;

N30 G71 U1 R1.5; N120 X81;

N40 G71 P45 Q55 U0.5 W0.2 F0.2; N125 G01 Z-33;

N45 G01 X80 Z0; N130 X60;

N50 X80 Z-70; N135 X85;

N51 X81; N136 G01 Z-44.5;

N55 G00 F Z2 M09 ; N140 X60 ;

N60 G28 U0 W0; N145 X85;

N65 G00 X100 Z100 T00 ; N146 G01 Z-66 ;

N70 M05; N150 X10;

N71 T0303 M08; N155 X81;

N72 G50 S3500; N156 G00 Z2 M09;

N75 G96 S250 M03;

N65 G00 X100 Z100 T00;



:0001 N70 M05; N0 G21 G40 G54 G90 G95; N71 T0303 M08; N1 G28 U0 W0; N72 G50 S3500; N75 G96 S250 M03; N2 T0101 M08; N3 G50 S3000; N80 G00 X81 Z2; N4 G96 S300 M03; N85 G41; N90 G70 P45 Q55 F0.2; N5 G00 X0 Z-0.5; N6 G00 X50; N95 X41; N100 G00 X100 Z100 T00; N10 G01 Z0 F0.2; N30 G71 U1 R1.5; N105 T0505; N40 G71 P45 Q55 U0.5 W0.2 F0.2; N110 G01 X41 Z-15 F0.08; N45 G01 X21 Z0; N115 X21; N50 X24 Z-1.5; N120 X41; N125 Z-52; N51 Z-23; N52 X40 Z-33.5; N130 X15; N53 Z-53; N125 X41; N55 G00 F Z2 M09; N130 G01 Z1; N60 G28 U0 W0; M30;



:0001

N0 G21 G40 G54 G90 G95 ; N56 G02 X35 Z-58 R5 ;

N1 G28 U0 W0; N57 G03 X25 Z-100 R85;

N2 T0101 M08; N58 X40;

N3 G50 S3000; N59 G00 F Z2 M09;

N4 G96 S300 M03; N60 G28 U0 W0;

N5 G00 X0 Z-0.5; N65 G00 X100 Z100 T00;

N6 G00 X40; N70 M05;

N10 G01 Z0 F0.2; N71 T0303 M08;

N30 G71 U1 R1.5; N72 G50 S3500;

N40 G71 P45 Q59 U0.5 W0.2 F0.2 ; N75 G96 S250 M03 ;

N45 G01 X10 Z0; N80 G00 X81 Z2;

N50 X12; N85 G41;

N51 Z-18;

N52 X15; N90 G70 P45 Q58 F0.2;

N53 Z-33; N95 X40;

N54 X25; N100 G00 X100 Z100 T00;

N55 Z-53; N105 T0505;

