```
10 0
                                                                                                                                                    1 (Arduino Uno R3)
                                                                  7 void setup()
                                                                8 (
                                                                         pinMode(temperaturePin, IMPUT);
pinMode(DCMotorPin, OUTPUT);
                                                                 9
                                                                11
12
13
                                                                          Serial.begin(9600);
OO UNO
                                                                14 word loop()
                                                                15 [
                                                                16
                                                                         tempAnalog = analogRead(temperatureFin);
                                                                         tempAnalog = analoghead(temperatureFin);
double tempCelsius = (double)tempAnalog/1024*5;
tempCelsius = tempCelsius - 0.5;
tempCelsius = tempCelsius * 100;
Serial.print("The temperature is ");
Serial.print(tempCelsius);
Serial.print("& Fan is: ");
                                                                         if(tempCelsius>25){
  DCMotorPower=1000;
  Serial.println("On");
                                                                            DCMotorPower=0;
                                                                             Serial.println("Off");
                                                                         analogWrite(DCMotorPin, DCMotorPower);
                                                              Serial Monitor
```



