

(a) chain, stiffness only
(b) truss, stiffness only
(c) chain, masses only
(d) truss, masses only
(e) chain, stiffness and masses
(f) truss, stiffness and masses
excited ω_r [rad/s]
10^0
10^1
10^2
10^3
10^4
10^5
s
optimized designs
explicit family
excited gap, optimized
ω