R2	Rc minimum	Umax (R _{1/4 de W})
100 Ohms	100 MOhms	5V !!
1000 Ohms	10 MOhms	15,8V
10000 Ohms	1MOhms	50V
100000 Ohms	90000 Ohms	158V