## byte8 t debug + value + DEBUG AM OK + DEBUG APT OK + DEBUG\_MCU\_OK + DEBUG PRESSURE OK + DEBUG MOTOR RUNNING + DEBUG STATE + DEBUG STATE + DEBUG STATE 3 + bits +Debug fields DebugHelper + pressure ok + mcu ok + apt ok + am ok + motor run + DebugHelper() + ~DebugHelper() + update() + update() + update() + show()