mean values confidence= 99.0% 100% Values of P 0.2 80% 0.5 coverage (%) 60% 8.0 0.9 40% 20% 0% -5 15 16 Transmission Range (m)