











Set charging current by selecting proper R2 1k2 - 1000mA .

1218V 1k5 - 780mA

2k - 580mA I = -----R2

4k - 300mA

(max 1A)

open source hardware CC-BY-SA

TITLE: LiFePO4 Power Board 3V3 REV: 1.0

EasyEDA

Company: wagiminator Sheet: 1/1 Drawn By: Stefan Wagner Date: 2020-07-03