

$$VOUT = 0.925 * -\frac{R2 + R3}{R3}$$



TITLE: MP2307 5V Buck Converter REV: 1.0

EasyEDA

Company: wagiminator

Drawn By: Stefan Wagner 2019-07-05

Sheet: 1/1