

Incident Review Q3 2026

Prepared by the operations team. Three incidents in the quarter, no injuries.

Incident 1 - 14 July 2026, Mannheim (KX-1)

A K-4 Kestrel was grounded mid-route after a lightning strike 9 km away; the 15/30 rule was applied and the drone waited at a safe landing point. The parcel arrived 41 minutes after the end of its Standard window, so the late-delivery refund applied.

Incident 2 - 2 August 2026, Rhine crossing near Ludwigshafen (KX-2)

A K-7 Heron released its payload early over the river bank. Root cause: a timing bug in latch firmware 3.1.4. The payload was recovered, but damaged. The fleet was updated to latch firmware 3.1.6 within 48 hours; no repeat since.

Incident 3 - 3 September 2026, Heidelberg (near miss)

A K-2 Sparrow came within 20 m of a newly erected construction crane that was missing from the map. New rule: construction-zone geofences are refreshed every Monday from the city's permit feed.

Actions

Action	Owner	Due
Weekly geofence refresh automated	M. Okafor	2026-10-15
Latch firmware canary rollout process	J. Lindqvist	2026-10-31
Lightning-hold waiting points added to all routes	A. Brandt	2026-11-30