

How many of a node's two dies fused each slice
of the slices fused at all in a node, 74% are fused on only ONE of its two dies — the two sockets are near-independent parts

