















Fusion 360 interface showing a 3D model of a machine vice.

The top menu bar includes: File, Assemble, Design, 3D Model, Sketch, Annotate, Inspect, Tools, Manage, View, Environments, Collaborate, Electromechanical, Fusion 360.

The toolbar below the menu bar includes: Place, Create, Free Move, Free Rotate, Show, Pattern, Mirror, Parameters, Purge, Create Derived Substitutes, Plane, Axis, Point, UCS, Simplify, and Simplification.

The left sidebar displays the Assembly tree:

- Model States: [Primary]
- Origin:
 - YZ Plane
 - XZ Plane
 - XY Plane
 - X Axis
 - Y Axis
 - Z Axis
 - Center Point
- Insert:2
- [o]:druckhuelse:1
 - Model States: [Primary]
 - Origin:
 - YZ Plane
 - XZ Plane
 - XY Plane
 - X Axis
 - Y Axis
 - Z Axis
 - Center Point
 - Insert:1
 - Insert:2
- [o]:Furungenesch:1
 - Model States: [Primary]
 - Origin:
 - YZ Plane

The main workspace shows the 3D model of the machine vice, which consists of a base plate, a clamping mechanism, and a handle. A callout indicates the "TOP" view. The bottom status bar shows "Home" and "3114205_Machine Vice.iام".

Page numbers: 33 | 17





























