


RK3576 N(PCIe/SATA/USB3)





Note:


Caps of between dashed red lines and U1000 should be placed under the U1000 package. Other caps should be placed close to the U1000 package


⊚ armsom			https://armsom.org/			
Project:	ArmSoM	-Sige5				
File:	RK3576-PCIe/SATA/USB3					
Date:	Tuesday, May 21, 2024			Rev:	V1.1	
Designed by:	Park	Reviewed by:	<checker></checker>	Sheet:	9 of 25	


5 4 3 2









































Revision History

Version	Date	Ву	Change Dsecription	Approved
V1.0	2024-03-27	SL Chen	First release;	
V1.1	2024-05-15	SL Chen	1.U1/U2 Pin5 connect to output; TF_DET_L connect to VCC_1V8_S3; J23 Pin2&Pin3 change position; 2.J25 MIPI_DPHY_CSI3_CAM_CLKOUT&MIPI_DPHY_CSI4_CAM_CLKOUT_CON change posi	ition;
	RY		SPY	
XIRKA			MURATIRA	M.
		B	ot 1800t	

№ armsom			https://armsom.org/			
	Project:	ArmSoM	-Sige5			
	File:	Revision	History			
	Date:	Wednesday	, May 22, 2024		Rev:	V1.1
	Designed by:	Park	Reviewed by:	<checker></checker>	Sheet:	25 of 25