

UNCLASSIFIED



## **CISCO NX OS SWITCH STIG REVISION HISTORY**

**01 October 2025**

**Developed by DISA for the DOD**

UNCLASSIFIED

# UNCLASSIFIED

| REVISION HISTORY   |   |                 |
|--|---|-----------------|
| Document Revised   | Description of Change   | Release Date    |
| - Cisco NX OS Switch NDM STIG, V3R4  | <b>Cisco NX OS Switch NDM STIG, V3R5:</b><br>- CISC-ND-001410 - Corrected syntax in Check and Fix Text.<br>- CISC-ND-000140 - Rule number updated due to changes in content management system.  | 01 October 2025 |
| - Cisco NX OS Switch NDM STIG, V3R3  | <b>Cisco NX OS Switch NDM STIG, V3R4:</b><br>- CISC-ND-001150 - Updated MD5 to SHA-256 in Check and Fix text.   | 02 July 2025    |
| - Cisco NX OS Switch NDM STIG, V3R2  | <b>Cisco NX OS Switch NDM STIG, V3R3:</b><br>- CISC-ND-001410 - Updated protocols from FTP and TFTP to SCP.<br>- CISC-ND-000470, CISC-ND-000490 - Rule number updated due to changes in content management system.  | 02 April 2025   |
| - Cisco NX OS Switch RTR STIG, V3R2  | <b>Cisco NX OS Switch RTR STIG, V3R3:</b><br>- CISC-RT-000120 - Combined with CISC-RT-000130.<br>- CISC-RT-000130 - Rolled up CCIs into CISC-RT-000120 and deleted duplicate requirement.   | 30 January 2025 |
| - Cisco NX OS Switch L2S STIG, V3R1<br><br>- Cisco NX OS Switch NDM STIG, V3R1 | <b>Cisco NX OS Switch L2S STIG, V3R2:</b><br>- CISC-L2-000010 - Removed requirement.<br><br><b>Cisco NX OS Switch NDM STIG, V3R2:</b><br>- CISC-ND-000290 - Corrected syntax error in the note.<br>- CISC-ND-001030 - Updated Check and Fix text to remove unneeded commands and fix syntax.<br>- CISC-ND-000530, CISC-ND-001200, CISC-ND-001210 - Removed FIPS mode requirement and replaced with commands to enable FIPS compliant protocols for services.<br>- CISC-ND-000530, CISC-ND-001200, CISC-ND-001210 - Updated Check and Fix procedure and removed note which applied to a now unsupported OS version.<br>- CISC-ND-001220 - Corrected syntax for Check and Fix from IOS-XE to NX-OS.<br>- Rule numbers updated due to change in content management system. | 24 October 2024 |

**UNCLASSIFIED**

| <b>REVISION HISTORY</b>              |   |                     |
|--------------------------------------|---|---------------------|
| <b>Document Revised</b>              | <b>Description of Change</b>  | <b>Release Date</b> |
| - Cisco NX OS Switch RTR STIG, V3R1  | <b>Cisco NX OS Switch RTR STIG, V3R2:</b><br>- CISC-RT-000070 - Removed requirement.<br>- CISC-RT-000120 - Rule updated due to changes in content management system.  |                     |
| - Cisco NX OS Switch L2S STIG, V2R3  | <b>Cisco NX OS Switch L2S STIG, V3R1:</b><br>- CISC-L2-000210, CISC-L2-000220, CISC-L2-000230, CISC-L2-000240, CISC-L2-000250, CISC-L2-000260, CISC-L2-000270 - Updated based on NIST SP 800-53 Rev. 5 changes.   | 24 July 2024        |
| - Cisco NX OS Switch NDM STIG, V2R8  | <b>Cisco NX OS Switch NDM STIG, V3R1:</b><br>- CISC-ND-000140, CISC-ND-000570, CISC-ND-000580, CISC-ND-000590, CISC-ND-000600, CISC-ND-001000, CISC-ND-001030, CISC-ND-001440 - Updated based on NIST SP 800-53 Rev. 5 changes.   |                     |
| - Cisco NX OS Switch RTR STIG, V2R3  | <b>Cisco NX OS Switch RTR STIG, V3R1:</b><br>- CISC-RT-000120, CISC-RT-000580, CISC-RT-000590, CISC-RT-000630, CISC-RT-000640 ,CISC-RT-000650, CISC-RT-000670, CISC-RT-000680, CISC-RT-000950 - Updated based on NIST SP 800-53 Rev. 5 changes.<br><br>- Because this is a major revision, version numbers were incremented to the next whole number.<br>- Rule numbers updated throughout due to changes in content management system. |                     |
| - Cisco NX OS Switch NDM STIG, V2R7  | <b>Cisco NX OS Switch NDM STIG, V2R8:</b><br>- CISC-ND-001220 - Added back requirement that had been removed.   | 24 April 2024       |
| - Cisco NX OS Switch NDM STIG, V2R6  | <b>Cisco NX OS Switch NDM STIG, V2R7:</b><br>- CISC-ND-001130, CISC-ND-001140 - Corrected syntax to correctly meet requirement.<br>- CISC-ND-000290 - Changed log-input parameter to only log.  | 24 January 2024     |
| - Cisco NX OS Switch L2S STIG, V2R2: | <b>Cisco NX OS Switch L2S STIG, V2R3:</b><br>- CISC-L2-000090 - Removed "and host" from check and fix text.   |                     |

# UNCLASSIFIED

| REVISION HISTORY                    |  |                 |
|-------------------------------------|--|-----------------|
| Document Revised                    | Description of Change  | Release Date    |
| - Cisco NX OS Switch NDM STIG, V2R5 | <b>Cisco NX OS Switch NDM STIG, V2R6:</b><br>- CISC-ND-000530, CISC-ND-001200, CISC-ND-001210 - Corrected syntax in check text. Removed note in fix text. Updated for style guide compliance.<br>- CISC-ND-000720 - Rule number updated due to changes in content management system.<br>- CISC-ND-001220 - Added requirement that was removed. Updated for style guide compliance.<br><br>- Revision History format for multipart STIGs revised to ensure clarity in the versioning. | 25 October 2023 |

| REVISION HISTORY |                                 |  |              |
|------------------|---------------------------------|--|--------------|
| Revision Number  | Document Revised                | Description of Change  | Release Date |
| V2R6             | - Cisco NX OS Switch STIG, V2R5 | <b>Cisco NX OS Switch L2S STIG, V2R2:</b><br>- CISC-L2-000190 - Updated check text for correct syntax.<br><br><b>Cisco NX OS Switch NDM STIG, V2R5:</b><br>- No change in this quarter.<br><br><b>Cisco NX OS Switch RTR STIG, V2R3:</b><br>- CISC-RT-000760, CISC-RT-000770 - Removed reference to QOS DODIN Technical Profile.   | 26 July 2023 |
| V2R5             | - Cisco NX OS Switch STIG, V2R4 | <b>Cisco NX OS Switch NDM STIG, V2R5:</b><br>- CISC-ND-000720 - Changed idle timeout to five minutes.<br>- CISC-ND-001370 - Changed requirement to utilize redundant authentication servers. Updated CCI.<br>- CISC-ND-001450 - Changed requirement to utilize redundant syslog servers. Updated CCI.<br><br><b>Cisco NX OS Switch RTR STIG, V2R2:</b><br>- No change in this quarter. | 07 June 2023 |

**UNCLASSIFIED**

| <b>REVISION HISTORY</b> |                                 |  |                     |
|-------------------------|---------------------------------|--|---------------------|
| <b>Revision Number</b>  | <b>Document Revised</b>         | <b>Description of Change</b>   | <b>Release Date</b> |
|                         |                                 | <b>Cisco NX OS Switch L2S STIG, V2R1:</b><br>- No change in this quarter.  |                     |
| V2R4                    | - Cisco NX OS Switch STIG, V2R3 | <b>Cisco NX OS Switch NDM STIG, V2R4:</b><br>- CISC-ND-000250, CISC-ND-001290 - Removed requirement; duplicate of CISC-ND-001260.<br>- CISC-ND-001220 - Removed requirement; default policy meets requirement.<br>- Updated title of STIG in content management system to remove hyphen in NX OS.<br>- Rule Keys updated due to changes in content management system.<br><br><b>Cisco NX OS Switch RTR STIG, V2R2:</b><br>- Updated title of STIG in content management system to remove hyphen in NX OS.<br>- Rule Keys updated due to changes in content management system.<br><br><b>Cisco NX OS Switch L2S STIG, V2R1:</b><br>- DISA migrated the Cisco NX OS Switch L2S STIG to a new content management system. The new content management system renumbered all Groups (V-numbers) and Rules (SV-numbers). With the new Group and Rule numbers, DISA incremented the version number from V1R1 to V2R1.<br>- Updated title of STIG in content management system to remove hyphen in NX OS. | 27 April 2023       |
| V2R3                    | - Cisco NX OS Switch STIG, V2R2 | <b>Cisco NX OS Switch NDM STIG, V2R3:</b><br>- CISC-ND-000150 - Updated Title, Check, and Fix to reflect the correct command.  | 27 October 2021     |
| V2R2                    | - Cisco NX OS Switch STIG, V2R1 | <b>Cisco NX OS Switch NDM STIG, V2R2:</b><br>- CISC-ND-000490 - Updated vulnerability discussion to allow secure network location for 'break glass' passwords.<br>- CISC-ND-000150 - Updated the check/fix content for correct 15 minute syntax.<br>- CISC-ND-000140 - Corrected configuration example in check and fix content.   | 23 April 2021       |

**UNCLASSIFIED**

| <b>REVISION HISTORY</b> |                                 |  |                     |
|-------------------------|---------------------------------|--|---------------------|
| <b>Revision Number</b>  | <b>Document Revised</b>         | <b>Description of Change</b>   | <b>Release Date</b> |
|                         |                                 | <b>Cisco NX OS Switch RTR STIG, V2R1:</b><br>- DISA migrated the Cisco NX OS Switch RTR STIG to a new content management system. The new content management system renumbered all Groups (V-numbers) and Rules (SV-numbers). With the new Group and Rule numbers, DISA incremented the version number from V1R1 to V2R1.<br>- CISC-RT-000236 - Added requirement to set hop limit to at least 32 for IPv6 stateless auto-configuration deployments.<br>- CISC-RT-000237 - Added requirement to prohibit use of IPv6 Site Local addresses.<br>- CISC-RT-000391 - Added requirement to suppress IPv6 Router Advertisements at external interfaces. |                     |
| V2R1                    | - Cisco NX OS Switch STIG, V1R1 | <b>Cisco NX OS Switch NDM STIG, V1R1:</b><br>- DISA migrated the Cisco NX OS Switch NDM STIG to a new content management system. The new content management system renumbered all Groups (V-numbers) and Rules (SV-numbers). With the new Group and Rule numbers, DISA incremented the version number from V1R1 to V2R1.<br>- CISC-ND-000290 - Added line to fix text for adding 'log' to deny ACLs.   | 22 January 2021     |
| V1R1                    | - NA                            | - Initial Release.   | 08 May 2020         |