Epoxy Granite CNC Mill - Feature # 67: Vacuum

Status: Priority: New Normal Author: Brandin Watson Category: Created: 07/13/2012 Assignee: Trenton Wilson **Updated:** 07/13/2012 Due date: 08/11/2012 Subject: Vacuum

Description

We need to create a vacuuming system to mitigate air bubbles in the epoxy granite. It needs to be able to fit around the assembled mold.

The cured EG may work perfectly for our purposes even with some bubbles but it is better safe than sorry.

History

12/08/2022 1/1