```
Point(1)={1.00000000,
                                    0.00000000,
                                                 1.000};
                       0.00000000.
Point(2)={0.99609000,
                                    0.00000000,
                                                 1.000};
                       0.00079500,
Point(3)={0.98441800,
                                                 1.000};
                       0.00314400.
                                    0.00000000.
Point(4)={0.96515900,
                                                 1.000};
                       0.00693900.
                                    0.00000000.
Point(5)={0.93860300.
                       0.01200900.
                                    0.00000000.
                                                 1.000};
Point(6)={0.90515300,
                       0.01814000.
                                    0.000000000.
                                                 1.000}:
Point(7)={0.86531800,
                                    0.000000000, 1.000};
                       0.02508100.
Point(8)={0.81970900,
                                    0.000000000, 1.000};
                       0.03256600,
Point(9)={0.76903100,
                       0.04032100.
                                    0.000000000 1.000}:
Point(10)={0.71407000.
                                     0.000000000. 1.000}:
                        0.04807000
Point(11)={0.65568500.
                        0.05554000.
                                     0.000000000. 1.000}:
Point(12)={0.59479300,
                        0.06245800,
                                     0.000000000, 1.000};
Point(13)={0.53235400,
                                     0.000000000, 1.000};
                        0.06855900.
Point(14)={0.46935800,
                                     0.000000000, 1.000};
                        0.07358400.
Point(15)={0.40681100.
                                     0.000000000. 1.000}:
                        0.07729100.
```