

That's correct!

Question 4

1 / 1 pts

Prioritization matrices are included under:

- ☐ cost accounting tools
- ☐ scheduling tools
- ☒ new seven QC tools
- ☐ acceptance sampling tools

Correct!

That's correct!

Question 5

1 / 1 pts

PDPC stands for:

- ☐ Planning Design Production Control
- ☒ Process Decision Program Chart
- ☐ Product Design Planning Chart
- ☐ Process Data Performance Curve

Correct!

That's correct!

Question 6

1 / 1 pts

Which of the following is one of the seven QC tools?

- ☐ activity network
- ☐ break-even chart
- ☒ check sheet
- ☐ matrix diagram

Correct!

That's correct!

Question 7

1 / 1 pts

Attribute data are generally:

- ☐ continuous in nature
- ☒ discrete in nature
- ☐ expressed in decimals only
- ☐ measured on a sliding scale

Correct!

That's correct!

Question 8

1 / 1 pts

Which of the following belongs to the new seven QC tools?

- ☐ check sheet
- ☐ histogram
- ☒ tree diagram
- ☐ stratification

Correct!

That's correct!

Question 9

1 / 1 pts

Quality control is intended to ensure that a product or service:

- ☐ neither innovation nor

Correct! →

maximizes variety

avoids all inspection

meets defined quality criteria

That's correct!

Question 10 1 / 1 pts

In SQC, measurement data are broadly classified into:

Correct! →

variable and attribute

planned and actual

fixed and variable

direct and indirect

That's correct!

Question 11 1 / 1 pts

One preliminary step in control procedure design is to:

Correct! →

choose statistical measures for the chart

eliminate sampling entirely

avoid recording data

reduce all process variation

That's correct!

Question 12 1 / 1 pts

The fishbone diagram is also known as the:

Correct! →

cause-and-effect diagram

affinity diagram

tree diagram

Pareto chart

That's correct!

Question 13 1 / 1 pts

A c-chart is generally used to monitor:

Correct! →

number of defects

machine speed

average sample size

process capability ratio

That's correct!

Question 14 1 / 1 pts

The first preliminary step in setting up a control procedure is to:

Correct! →

record inspection data

finalize production cost

select the quality characteristics to be controlled

choose statistical measures

That's correct!

Question 15

1 / 1 pts

Flowcharts are mainly used to:

Correct!

- ☒ present a process graphically
- ☐ measure product durability
- ☐ compute control limits
- ☐ classify defects by cost

That's correct!

Question 16

1 / 1 pts

An accept/reject test of a shaft is an example of:

Correct!

- ☐ variable data
- ☒ attribute data
- ☐ continuous data
- ☐ ratio analysis

That's correct!

Question 17

1 / 1 pts

While setting up a control procedure, the manufacturer should analyze the production process to:

Correct!

- ☒ find causes of irregularities
- ☐ estimate tax burden
- ☐ classify customer income
- ☐ determine advertising budget

That's correct!

Question 18

1 / 1 pts

Statistical Process Control (SPC) deals with decisions related to:

Correct!

- ☒ specification, production, and inspection
- ☐ warehousing and dispatch
- ☐ recruitment and training
- ☐ advertising and pricing

That's correct!

Question 19

1 / 1 pts

Pareto charts are based on the work of:

Correct!

- ☐ Philip Crosby
- ☐ W. Edwards Deming
- ☐ Walter Shewhart
- ☒ Vilfredo Pareto

That's correct!

Question 20 1 / 1 pts

Joseph M. Juran popularized Pareto's work by suggesting that:

- ☐ inspection replaces prevention
- ☐ all causes are equally important
- ☒ 80% of problems come from 20% of causes
- ☐ variation should be ignored

Correct!

That's correct!

Quiz Score: 20 out of 20

◀ Previous

Next ▶