## STM32F401 Pin Mapping

STIVISET TOT I III WIGPPING		
Control Pilot	lot Signal Control	PA1
USART Header Connections	ader TX	PA2
	ader RX	PA3
	ader Clock	PA4
External SPI Display Header	y Header - SCK	PA5
	y Header - MISO	PA6
	y Header - MOSI	PA7
	y Header - Reset	PA8
	y Header - DC	PA10
MCU Programming		PA13
Connector		PA14
Programmable	lot Status Led 1	PC1
	lot Status Led 2	PC2

Control Pilot Status Led 3

Control Pilot Status Led 4

Control Pilot Voltage Detection

AFE3010 Alarm Fault Detection

MCU Main Relay Control

ADE7953 CF2 Signal

ADE7953 CF1 Signal

ADE7953 RX

ADE7953 TX

ADE7953 IRQ

SPI Display CS

SWD

PC3

PC4

PC5

PBO

PC6

PB7

PC8

PB<sub>1</sub>

PB3

PB9

**PB13** 

**PB14** 

Status LEDs

ADE7953 Indicator

Connections

**USART 6** 

ADE7953 Interrupt

**Control Pilot** 

MCU Programming

SPI Display Header

Leakage Detection

**Charging Control**