

PM 117915.1



Work Order

117915.1

Location	ERIE	Erie Hall (Caution Mca)	Room	M102
Equipment	CR01-ERIE	CONDENSATE RECEIVER	Requester	
Serial Number			Contact	
PM Number	703		Phone	

Request CONDENSATE REC INS

- < > < > 1. CHECK COUPLING SHAFT ALIGNMENT ON PUMPS
- < > < > 2. REMOVE PACKING AND REPLACE IF APPLICABLE
- < > < > 3. CLEAN STRAINERS
- < > < > 4. REPLACE OR RENEW STRAINER GASKETS IF NEEDED
- < > < > 5. CHANGE OIL OR GREASE IF APPLICABLE
- < > < > 6. REPACK AND LUBRICATE VALVES IF NEEDED
- < > < > 7. MAKE SURE DRAIN LINES ARE CLEAR FROM PUMPS
- < > < > 8. CHECK THAT TANK FLOAT IS WORKING PROPERLY
- < > < > 9. MAKE SURE CHECK VALVES ARE HOLDING
- < > < > 10. MAKE SURE AREA IS CLEAN AND DRY AROUND RECEIVER

Status	CLOSE	Open Date	1/16/2001	Procedure	CONDR INSP
Priority		Complete Date	11/9/2001	Craft	ENG
Employee	JOHN GARTNER	Target Date	11/9/2001	Crew	

Estimates Hours **0.00** Labour **0.00** Material **0.00** Service **0.00** Tools **0.00** Total **0.00**

Estimate Labour

Employee	Description	Craft	Hours	Rate	Total Cost
820			0.05	\$0.00	\$0.00
			0.05		\$0.00

Actuals Hours **2.00** Labour **65.00** Material **0.00** Service **0.00** Tools **0.00** Total **65.00**

Actual Labour

Employee	Description	Craft	Hours	Rate	Total Cost

820			2.00	\$32.50	\$65.00
			2.00		\$65.00

Completion Remark: COMPLETE

☒Completed **By:** 820 **Comp Date:** 11/9/2001 **Comp Time:** 0:0 **Hours:** 2.00

Equip. Instructions:

TransDate	Empid	CreatedBy	Note
-----------	-------	-----------	------