

Example Test Jig Photos:










Plated through hole – consult data sheet for size (1.5mm?)

Can go straight into unpopulated through hole

Can go straight into unpopulated through hole connector pads.


Exposed pad – bigger = more reliable (2mm)

https://learn.adafruit.com/how-to-build-a-testing-fixture/solder-pogo-pins




829-22-002-20-001101CONNECTOR, HEADER, 2POS, 1ROW, 2.54MM


















https://youtu.be/mVW83boEbE0?t=53